

INSPECTION SHEET 検品書  
CRAWLER DRILL クローラドリル

MAKE	FURUKAWA	MODEL	HCR9-DS
SERIAL	511104	STAMP	511104
HRメーター	EG 7799HR / DRIFTER 3239HR	YEAR	1994 YR
CAB/CNP	<input checked="" type="radio"/> CAB / <input type="radio"/> CNP / <input type="radio"/> NONE	SHOE	300G
DRIFTER MODEL	HD609-4026		

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<input checked="" type="radio"/> OK · Attn	
Blow-By	<input checked="" type="radio"/> OK · Attn	
Sound	<input checked="" type="radio"/> OK · Attn	
Oil	<input checked="" type="radio"/> OK · Attn	
Exhaust Color	<input checked="" type="radio"/> OK · Attn	
US EPA	YES · <input checked="" type="radio"/> NO	
<b>MAIN PUMP</b>		
Sound	<input checked="" type="radio"/> OK · Attn	
Oil leakage	<input checked="" type="radio"/> OK · Attn	
Power	<input checked="" type="radio"/> OK · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<input checked="" type="radio"/> OK · Attn	
Oil Cooler	OK · <input checked="" type="radio"/> Attn	漏れ有(裏側の為、場所未確認)*
<b>OPERATING SYSTEM</b>		
Swing	OK · Attn	
Travel	<input checked="" type="radio"/> OK · Attn	
<b>INTERIOR</b>		
Operator's Seat	OK · <input checked="" type="radio"/> Attn	背もたれ欠損 破れ NO BACK WREST, CUTS
Inside Cover	OK · <input checked="" type="radio"/> Attn	欠落有 DAMAGED
Glasses	OK · <input checked="" type="radio"/> Attn	右前ガラスヒビ有 RIGHT FRONT CRACKED
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
<b>DRIFTER HYDR.</b>		
Lift	<input checked="" type="radio"/> OK · Attn	
Swing	<input checked="" type="radio"/> OK · Attn	
Tilt	<input checked="" type="radio"/> OK · Attn	
Slide	OK · <input checked="" type="radio"/> Attn	シリンダー油漏れ有 CYL: OIL LEAKING

<b>UNDERCARRIAGE :</b> See Photos. 写真参照	
<b>COMMENT</b>	
<b>Guide(Slide Length)</b>	mm
<b>Rod Changer</b>	<input checked="" type="radio"/> YES · NO
<b>Drifter</b>	<input checked="" type="radio"/> OK · Attn
<b>Compressor</b>	<input checked="" type="radio"/> OK · Attn
<b>Blow</b>	<input checked="" type="radio"/> OK · Attn
<b>BATTERY</b>	<input checked="" type="radio"/> OK · NG
*LEAKING FROM BACK SIDE, CANNOT CHECK THE PARTICULER PART	
EGストップ不良	
計器不良	
コンプレッサーオイルタンク付近より漏れ有	
ドリル欠品	
EG STOPPER: NOT WORKING	
METERS: NOT WORKING	
ARPUND COMPRESSOR OIL TANK: OIL LEAKING	
NO DRILLS	