## INSPECTION SHEET 検品書 OTHER その他

MAKE													
SERIAL 480	INSPECTION	ION DATE	2024/11/19	CA	TEGORY	BREAKER for 0.25m3							
HR METER   UNKNOWN   HR   Odometer   km   YEAR   CAB / ROPS CAB / CAB / ROPS CAP / CNP / NONE   SHOE   TIRE   TIRE   ENGINE   MODEL   S/N   FAIR · Attn   A LITTLE · MIDDLE · SEVERE   Exhaust Color FAIR · Attn   EPA   YES · NO	MAKE		токи					TNB-6M-US					
ENGINE MODEL S/N Oil leakage FAIR · Attn Oil FAIR · Attn Sound FAIR · Attn EPA YES · NO  CONDITION FAIR · Attn EPA YES · NO  CONDITION FAIR · Attn Attn Attn Attn Attn Attn Attn At	SERIAL	-	480					NOT FOUND					
ENGINE MODEL S/N Oil leakage FAIR・Attn Oil FAIR・Attn Blow-By FAIR・Attn A LITTLE・MIDDLE・SEVERE Exhaust Color FAIR・Attn Sound FAIR・Attn EPA YES・NO  CONDITION FAIR・Attn Attn 未確認 OPERATION: NOT CHECKED ホース1本、ロックボルトカラー欠 SOME HOSE & SOME LOCK BOLT COLLAR FOR PIN: MISSING  UNDERCARRIAGE: See Photos. 写真参照 RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) -	HR METER	R UNK	UNKNOWN HR Odometer					km YEAR YR					
Oil FAIR・Attn Blow-By FAIR・Attn A LITTLE・MIDDLE・SEVERE Exhaust Color FAIR・Attn Sound FAIR・Attn FPAIR・Attn EPA YES・NO CONDITION FAIR・Attn EPA YES・NO TOUR TOUR TOUR TOUR TOUR TOUR TOUR TOU	CAB/CNP	P ROPS CAR	B / CAB / ROPS CN	E			TIRE						
Blow-By FAIR · Attn A LITTLE · MIDDLE · SEVERE Exhaust Color FAIR · Attn Sound FAIR · Attn PAIR · At	ENGINE	MOE	MODEL										
Sound FAIR・Attn EPA YES・NO  CONDITION FAIR ・ Attn	Oil leakage	ge FAIR · Attn	FAIR · Attn				Oil	FAIR • Attn					
CONDITION FAIR ・ Attn 未確認 OPERATION: NOT CHECKED ホース1本、ロックボルトカラー欠 SOME HOSE & SOME LOCK BOLT COLLAR FOR PIN: MISSING UNDERCARRIAGE: See Photos. 写真参照 RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) – COMMENT	Blow-By	y FAIR · Attn	FAIR · Attn A LITTLE • MIDDLE • SEVERE				ust Color	FAIR • Attn					
未確認 OPERATION: NOT CHECKED ホース1本、ロックボルトカラー欠 SOME HOSE & SOME LOCK BOLT COLLAR FOR PIN: MISSING  UNDERCARRIAGE: See Photos. 写真参照  RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) -  COMMENT	Sound	FAIR · Attn	FAIR · Attn					YES • NO					
ホース1本、ロックボルトカラー欠 SOME HOSE & SOME LOCK BOLT COLLAR FOR PIN: MISSING  UNDERCARRIAGE: See Photos. 写真参照  RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) –  COMMENT	CONDI	DITION											
UNDERCARRIAGE: See Photos. 写真参照  RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) —  COMMENT	未確認 OPERATION: NOT CHECKED												
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)  COMMENT	ホース1本、ロックボルトカラー欠 SOME HOSE & SOME LOCK BOLT COLLAR FOR PIN: MISSING												
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)  COMMENT	UNDERCARRIAGE: See Photos. 写真参照												
50 φ × 182mm	COMMENT												
	$50\phi imes182$ mm												

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)