

INSPECTION SHEET 検品書
OTHER その他

| | | | | | |
|-----------------|--|----------|----------|--------|------|
| INSPECTION DATE | 2023/9/14 | CATEGORY | BREAKER | | |
| MAKE | OKADA | | MODEL | OUB505 | |
| SERIAL | UNKNOWN | | STAMP | 1470 | |
| HR METER | - | HR | Odometer | km | YEAR |
| CAB/CNP | ROPS CAB / CAB / ROPS CNP / CNP / NONE | | SHOE | | TIRE |

| | | | | | |
|-------------|-------------|----------------------------|---------------|-------------|--|
| ENGINE | MODEL | S/N | | | |
| Oil leakage | FAIR · Attn | | Oil | FAIR · Attn | |
| Blow-By | FAIR · Attn | A LITTLE · MIDDLE · SEVERE | Exhaust Color | FAIR · Attn | |
| Sound | FAIR · Attn | | EPA | YES · NO | |

| | | |
|----------------------------|-------------|--|
| CONDITION | FAIR · Attn | |
| 未確認 OPERATION: NOT CHECKED | | |

| | | |
|--|---|--|
| UNDERCARRIAGE : See Photos. 写真参照 | | |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | - | |
| COMMENT | | |
| 45φ × 190mm | | |
| ピン2本欠 2 PINS: MISSING | | |
| 左右本体接続ホース欠 2 HOSES: MISSING | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 | |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。