

INSPECTION SHEET 検品書
CARRY DUMP キャリーダンプ

INSPECTION DATE	2024/4/3	MAKE	KUBOTA	MODEL	RY601D-3
SERIAL	B16027		STAMP	NOT FOUND	
HR METER	346	HR	Odometer	km	YEAR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / <u>NONE</u>		SHOE	200R	TIRE

ENGINE : MODEL		S/N		6GL1405	
Oil leakage	<u>FAIR</u> · Attn				
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE			
Sound	<u>FAIR</u> · Attn				
Oil	<u>FAIR</u> · Attn				
Exhaust Color	<u>FAIR</u> · Attn				
US EPA	YES · <u>NO</u>				
OPERATION PUMP					
Sound	<u>FAIR</u> · Attn				
Oil leakage	<u>FAIR</u> · Attn				
Power	<u>FAIR</u> · Attn				
COOLING SYSTEM					
Radiator	<u>FAIR</u> · Attn				
Oil Cooler	<u>FAIR</u> · Attn				
TRANSMISSION & TRAVEL					
T/M TYPE	PS · <u>DD</u>	No. OF GEARS	GEARS		
Transmission	<u>FAIR</u> · Attn				
Travel	<u>FAIR</u> · Attn				
Swing	<u>FAIR</u> · Attn				
Articulate	<u>FAIR</u> · Attn				
FOOT BRAKE	<u>FAIR</u> · Attn				
PARKING BRAKE	<u>FAIR</u> · Attn				
INTERIOR See Photos. 写真参照					
Operator's Seat	<u>FAIR</u> · Attn				
Inside Cover	<u>FAIR</u> · Attn				
Glasses	<u>FAIR</u> · Attn				
AirCon	A/C · H/C · H only · C only · <u>None</u>				

MAIN FRAME	
MAIN FLAME	<u>FAIR</u> · Attn
VESSEL	
VESSEL	<u>FAIR</u> · Attn
REAR GATE TYPE	NORMAL · L-GATE (FLAT)
REAR GATE	<u>FAIR</u> · Attn
UNDERCARRIAGE: See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
<div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div> <div style="border-bottom: 1px dotted black; margin-bottom: 5px;"></div>	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。