

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2024/4/4	MAKE	KUBOTA	MODEL	U-30-5
SERIAL	79565		STAMP	79565	
HR METER	5629	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <b>CNP</b> / NONE		SHOE	300R	

ENGINE : MODEL		S/N	7FA9377
Oil leakage	<b>FAIR</b> · Attn		
Blow-By	<b>FAIR</b> · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<b>FAIR</b> · Attn		
Oil	<b>FAIR</b> · Attn		
Exhaust Color	<b>FAIR</b> · Attn		
US EPA	YES · <b>NO</b>		

MAIN PUMP	
Sound	<b>FAIR</b> · Attn
Oil leakage	<b>FAIR</b> · Attn 上部油漏れ小 UPPER PART: OIL LEAKING
Power	<b>FAIR</b> · Attn

COOLING SYSTEM	
Radiator	<b>FAIR</b> · Attn
Oil Cooler	<b>FAIR</b> · Attn

OPERATING SYSTEM	
Swing	<b>FAIR</b> · Attn
Travel	<b>FAIR</b> · Attn

INTERIOR See Photos. 写真参照	
Operator's Seat	<b>FAIR</b> · Attn 破れ小 CUTS
Inside Cover	<b>FAIR</b> · Attn
Glasses	<b>FAIR</b> · Attn
AirCon	A/C · H/C · H only · C only · <b>None</b>

BOOM / ARM / BKT	
Boom	<b>FAIR</b> · Attn
Boom Cylinder	<b>FAIR</b> · Attn
Arm	<b>FAIR</b> · Attn
Arm Cylinder	<b>FAIR</b> · Attn
BKT	<b>FAIR</b> · Attn ガタ大 MUCH LOOSE
BKT Cylinder	<b>FAIR</b> · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT 左シュー亀裂あり LEFT RUBBER TRACK: MUCH CRACKED	
BKT	<b>STD</b> / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	LONG · <b>WRIST</b>
Multi	MULTI · <b>2</b> · NO
ARM-CRANE	YES · <b>NO</b>
BLADE	<b>YES</b> · NO
OFFSET	YES · <b>NO</b>
OFFSET Cylinder	<b>FAIR</b> · Attn
Piping	<b>YES</b> · NO Breaker only · <b>Multi</b>

COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。