

INSPECTION SHEET 検品書  
FORK LIFT フォークリフト

INSPECTION DATE	2024/12/9	MAKE	MITSUBISHI	MODEL	FDE25T
SERIAL	F18D-72549		STAMP	F18D-72549	
HR METER	2643	HR	Odometer	-	km
CAB/CNP	CAB / <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">CNP</span> / NONE		TIRE SIZE	F: 5.50-15 SOLID / R: 6.00-9 SOLID	
MAX LIFTING HEIGHT	4.0	m	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">VIEW</span> MONO	FORK LENGTH	900 mm
FORK SPEC	ヒンジフォーク HINGED FORK				

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">FAIR</span> · Attn	
Blow-By	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">FAIR</span> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">FAIR</span> · Attn	
Oil	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">FAIR</span> · Attn	
Exhaust Color	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">FAIR</span> · Attn	
US EPA	YES · <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">NO</span>	
<b>OPERATION PUMP</b>		
Sound	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">FAIR</span> · Attn	
Oil leakage	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">FAIR</span> · Attn	
Power	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">FAIR</span> · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">FAIR</span> · Attn	
Oil Cooler	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">FAIR</span> · Attn	
<b>TRANSMISSION &amp; TRAVEL</b>		
T/M TYPE	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">PS</span> · DD	
Transmission	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">FAIR</span> · Attn	
Travel	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">FAIR</span> · Attn	
FOOT BRAKE	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">FAIR</span> · Attn	
PARKING BRAKE	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">FAIR</span> · Attn	
<b>INTERIOR</b> See Photos. 写真参照		
Operator's Seat	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">FAIR</span> · <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">Attn</span>	破れあり A LITTLE DAMAGED
Inside Cover	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">FAIR</span> · Attn	
Glasses	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">FAIR</span> · Attn	
AirCon	A/C · H/C · H only · C only · <span style="border: 1px solid black; border-radius: 50%; padding: 2px;">None</span>	
<b>HYDRAULICS</b>		
MAST Cylinder	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">FAIR</span> · Attn	
TILT Cylinder	<span style="border: 1px solid black; border-radius: 50%; padding: 2px;">FAIR</span> · Attn	

<b>UNDERCARRIAGE :</b> See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
タイヤ摩耗あり TIRES: WORN	
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。