

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/3/17	MAKE	KOMATSU	MODEL	PC50UU-2E
SERIAL	13681		STAMP	13681	
HR METER	6056	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	400R	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	
Travel	FAIR · Attn	*1
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	*2
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	ガタあり LOOSE
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	*3
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	ガタあり LOOSE
BKT Cylinder	FAIR · Attn	にじみあり OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
トラックフレーム真後ろ側補修跡あり	
REAR PART OF MAIN FRAME: REPAIRED	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO *4
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
バッテリー前カバー、作動油タンクカバー欠	
FRONT RIGHT TOP COVER FOR BATTERY	
& TOP COVER FOR HYDRAULIC OIL TANK: MISSING	
左走行レバー戻り悪い LEFT TRAVEL LEVER: HARD TO RETURN	
アクセルレバー不良(高回転のまま戻らない)	
ACCELERATOR LEVER: MALFUNCTION	
(ACCELERATOR WIRE: UNABLE TO RETURN FROM THE FULL THROTTLE POSITION)	
*1 増速ペダル不良 HI/LO SHIFTING PEDAL: MALFUNCTION	
*2 CABドアアクリル板加工あり DOOR GLASSES: ACRYLIC BOARDS	
*3 テレスコピックアーム、ガタ、クラックあり TERLESCOPIC ARM, LOOSE, CRACKED	
*4 干渉防止不良 ANTI-INTERFERENCE SYSTEM: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。