

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2025/4/7	MAKE	KUBOTA	MODEL	RX-306E
SERIAL	21716		STAMP	21716	
HR METER	4817	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> / NONE		SHOE	300R	

<b>ENGINE : MODEL</b>		<b>S/N</b>	7GS6247
Oil leakage	<u>FAIR</u> · Attn		
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	<u>FAIR</u> · Attn		
Oil	<u>FAIR</u> · Attn		
Exhaust Color	<u>FAIR</u> · Attn		
US EPA	YES · <u>NO</u>		
<b>MAIN PUMP</b>			
Sound	<u>FAIR</u> · Attn		
Oil leakage	<u>FAIR</u> · Attn		
Power	<u>FAIR</u> · Attn		
<b>COOLING SYSTEM</b>			
Radiator	<u>FAIR</u> · Attn		
Oil Cooler	<u>FAIR</u> · Attn		
<b>OPERATING SYSTEM</b>			
Swing	<u>FAIR</u> · Attn		
Travel	<u>FAIR</u> · Attn		
<b>INTERIOR See Photos. 写真参照</b>			
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY		
Operator's Seat	<u>FAIR</u> · Attn		
Glasses	<u>FAIR</u> · Attn		
AirCon	A/C · H/C · H only · C only · <u>None</u>		
<b>BOOM / ARM / BKT</b>			
Boom	<u>FAIR</u> · Attn	ガタあり LOOSE	
Boom Cylinder	<u>FAIR</u> · Attn		
Arm	<u>FAIR</u> · Attn		
Arm Cylinder	<u>FAIR</u> · Attn		
BKT	<u>FAIR</u> · Attn		
BKT Cylinder	<u>FAIR</u> · Attn		

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
<b>COMMENT</b>	
<div style="border: 1px solid black; padding: 5px;">                 BKT <u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ( )             </div> <div style="border: 1px solid black; padding: 5px;">                 Lever LONG · <u>WRIST</u> </div> <div style="border: 1px solid black; padding: 5px;">                 Multi MULTI · <u>2</u> · NO             </div> <div style="border: 1px solid black; padding: 5px;">                 ARM-CRANE YES · <u>NO</u> </div> <div style="border: 1px solid black; padding: 5px;">                 BLADE <u>YES</u> · NO             </div> <div style="border: 1px solid black; padding: 5px;">                 OFFSET <u>YES</u> · NO             </div> <div style="border: 1px solid black; padding: 5px;">                 OFFSET Cylinder <u>FAIR</u> · Attn             </div> <div style="border: 1px solid black; padding: 5px;">                 Piping YES · <u>NO</u> Breaker only · Multi             </div>	
<b>COMMENT</b>	
E/Gフードダンパー不良 ENGINE HOOD DAMPER: MALFUNCTION	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。