

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/5/7	MAKE	KOMATSU	MODEL	D41P-6	
SERIAL	50006			STAMP	D41P6-50006	
HR METER	7347	HR	SHOE	700LGP	YEAR	YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL		6D102E-1	S/N	26249259
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			

OPERATION PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	

TRANSMISSION & TRAVEL

T/M TYPE	PS · DD	DIFF. STEERING	YES · (NO)
Transmission	FAIR · Attn		
Travel	FAIR · Attn		

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN • FAIR • DIRTY				
Operator's Seat	FAIR • Attn				
Glasses	FAIR • Attn				
AirCon	A/C •	H/C •	H only •	C only •	None

BLADE & CYLINDERS

BLADE	FAIR・Attn	クラック、補修跡あり CRACKED, REPAIRED
CYLD.(R)	FAIR・Attn	
CYLD.(L)	FAIR・Attn	
TILT CYLD	FAIR・Attn	
ANGLE CYLD	FAIR・Attn	

UNDERCARRIAGE See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
---	----------

COMMENT

Ripper	MULTI ▀ S/S	Shanks	PCS
Ripper CYLD.	FAIR ▀ Attn		
EQUALIZER BAR	FAIR ▀ Attn		

COMMENT

両側E/Gサイドカバーダンパー不良

ENGINE SIDE COVER DAMPERS: MALFUNCTION

RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **4**

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。