

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/6/4	MAKE	KOMATSU	MODEL	D65PX-17
SERIAL	3023		STAMP	KMT0D117CFA003023	
HR METER	3253	HR	SHOE	940LGP	YEAR YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER		CAB/CNP	(ROPS CAB) / CAB / ROPS CNP / CNP / NONE	

ENGINE : MODEL 6D114E-5 S/N 26904019	
Oil leakage	(FAIR) · Attn
Blow-By	(FAIR) · Attn A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn
Oil	(FAIR) · Attn
Exhaust Color	(FAIR) · Attn
US EPA	YES · (NO)
OPERATION PUMP	
Sound	(FAIR) · Attn
Oil leakage	(FAIR) · Attn
Power	(FAIR) · Attn
COOLING SYSTEM	
Radiator	(FAIR) · Attn
Oil Cooler	(FAIR) · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	(PS) · DD DIFF. STEERING (YES) · NO
Transmission	(FAIR) · Attn
Travel	(FAIR) · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · (FAIR) · DIRTY
Operator's Seat	(FAIR) · Attn *1
Glasses	(FAIR) · Attn
AirCon	(A/C) · H/C · H only · C only · None
BLADE & CYLINDERS	
BLADE	(FAIR) · Attn
CYLD.(R)	(FAIR) · Attn
CYLD.(L)	(FAIR) · Attn
TILT CYLD	(FAIR) · Attn
ANGLE CYLD	FAIR · Attn

UNDERCARRIAGE See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
Ripper	MULTI · S/S Shanks PCS
Ripper CYLD.	FAIR · Attn
EQUALIZER BAR	FAIR · Attn
COMMENT	
*1 破れあり、ヘッドレスト欠 CUTS, HEADREST: MISSING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。