

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/8/26	MAKE	TADANO	MODEL	GR-600N-1
SERIAL No.	PLATE : FD5522		STAMP : TR600-0520		
HR METER	8345	HR	Odometer	127420	km
TIRE SIZE	505/95R25		YEAR	YR	

<b>ENGINE : MODEL</b>		<b>S/N</b>
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Blow-By	<input checked="" type="radio"/> FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil	<input checked="" type="radio"/> FAIR · Attn	
Exhaust Color	<input checked="" type="radio"/> FAIR · Attn	
<b>OPERATION PUMP</b>		
Sound	<input checked="" type="radio"/> FAIR · Attn	
Oil leakage	<input checked="" type="radio"/> FAIR · Attn	
Power	<input checked="" type="radio"/> FAIR · Attn	
<b>COOLING SYSTEM</b>		
Radiator	<input checked="" type="radio"/> FAIR · Attn	
Oil Cooler	<input checked="" type="radio"/> FAIR · Attn	
<b>OPERATING SYSTEM</b>		
Computer	<input checked="" type="radio"/> OK · NG	
Swing	<input checked="" type="radio"/> FAIR · Attn	
Travel	<input checked="" type="radio"/> FAIR · Attn	
<b>TRANSMISSION</b>		
Transmission	<input checked="" type="radio"/> FAIR · Attn	*1
No. OF GEARS	4	GEARS
4WD	<input checked="" type="radio"/> 4WD · 6WD	
<b>INTERIOR See Photos. 写真参照</b>		
INTERIOR COND.	CLEAN · <input checked="" type="radio"/> FAIR ·	DIRTY
Operator's Seat	<input checked="" type="radio"/> FAIR · Attn	
Glasses	<input checked="" type="radio"/> FAIR · Attn	
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None	
<b>COMMENT</b>		

<b>BOOM</b>				
No. of Section	6	SECTIONS		
CRACK/ENFORCEMENT	<input checked="" type="radio"/> FAIR · Attn			
DERRICKING CYL.	<input checked="" type="radio"/> FAIR · Attn			
EXTENSION CYL.	<input checked="" type="radio"/> FAIR · <input checked="" type="radio"/> Attn	油漏れあり OIL LEAKING		
JIB	<input checked="" type="radio"/> YES · NO			
JIB TYPE	STD · <input checked="" type="radio"/> PWR			
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO			
FREE FALL	YES · <input checked="" type="radio"/> NO			
HOOK	60t, 25t, BALL			
<b>UNDERCARRIAGE : See Photos. 写真参照</b>				
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)				3
TIRE WEAR	FAIR · WORN · <input checked="" type="radio"/> UNEVEN WEAR			
<b>COMMENT</b>				
<b>OUTRIGGERS</b>				
OUTRIGGERS	X · <input checked="" type="radio"/> H			
OUTRIGGERS COND.	<input checked="" type="radio"/> FAIR · Attn			
Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R
<b>COMMENT</b>				
縦シリンダー4本にじみあり ALL JACK CYLINDERS: OIL OOZING				
*1 ミッション付近、トルコン下部にじみあり				
*1 AROUND TRANSMISSION & LOWER PART OF TORQUE CONVERTER: OIL OOZING				
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。