

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/8/7	MAKE	KOMATSU	MODEL	WA100-3E
SERIAL	53227			STAMP	W057-5?227 SOME LETTER: UNREADABLE
HR METER	1940	HR	Odometer	-	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / <u>CNP</u> NONE			TIRE SIZE	16.9-24

ENGINE : MODEL		S/N
Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	YES · <u>NO</u>	
OPERATION PUMP		
Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	
COOLING SYSTEM		
Radiator	<u>FAIR</u> · Attn	
Oil Cooler	<u>FAIR</u> · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	<u>PS</u> · DD	
Transmission	<u>FAIR</u> · Attn	
Travel	<u>FAIR</u> · Attn	
FOOT BRAKE	<u>FAIR</u> · Attn	
PARKING BRAKE	<u>FAIR</u> · Attn	*1
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY	
Operator's Seat	<u>FAIR</u> · Attn	破損あり BROKEN
Glasses	<u>FAIR</u> · Attn	
AirCon	A/C · H/C · H only · C only · <u>None</u>	
FRONT & CYLINDERS		
Arm	<u>FAIR</u> · Attn	
Bell crank	<u>FAIR</u> · Attn	
Bucket	<u>FAIR</u> · Attn	*2
Articulate	<u>FAIR</u> · Attn	左シリンダー油漏れ小 LEFT CYLINDER: OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	<u>FAIR</u> · <u>WORN</u> · UNEVEN WEAR
COMMENT	
STEERING TYPE <u>WHEEL STEERING</u> / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES · <u>NO</u>
ATTACHMENTS	
STD BKT	<u>YES</u> · OTHER
BLADE	YES · <u>NO</u> Piping for Tilt YES · <u>NO</u>
COMMENT	
全体的にホースの劣化多い MANY HYDRAULIC HOSES: DETERIORATED	
*1 フットペダル手で引かないと解除できない	
*1 NEED TO PULL THE PEDAL BY ONESELF TO RELEASE	
*2 シリンダーにじみ、穴あり CYLINDER: OIL OOZING, HUGE HOLES	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。