## INSPECTION SHEET 検品書 CRAWLER CRANE クローラクレーン

INSPECTIO	ON DATE	2025/7/24	MAKI	E	MAEDA		MODEL	N	MC-235CW		
SERIAL No.	PLATE :	PLATE: X0		0419				X00419			
HR METER	17	43 HR	SHOE		180R		YEAR	2	2007	YR	
ENGINE: MODEL S/N					INTERIOR	INTERIOR See Photos. 写真参照					
Oil leakage	FAIR · Attn	油汚れあり OIL	STAINS		INTERIOR COND.	C	LEAN •	FAIR	• DIRTY		
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE				Operator's Seat	FAIR •	R • Attn				
Sound	FAIR · Attn				Glasses	FAIR •	Attn				
Oil	FAIR · Attn				AirCon	A/C	• H/C	• H only	· C only ·	None	
Exhaust Color	FAIR · Attn		UNDERCARRIAGE: See Photos. 写真参照								
OPERATION PUMP					RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)						
Sound FAIR · Attn					COMMENT						
Oil leakage	FAIR · Attn				-						
Power	FAIR · Attn				-						
COOLING SYSTEM					WEIGHT	-	-				
Radiator	FAIR · Attn				ноок		2.37t				
Oil Cooler	FAIR · Attn				LIFTER		YES · NO				
OPERATING SYSTEM					COMMENT						
Computer OK · NG					カニクレーン SPIDER CRANE						
Swing FAIR · Attn					5段ブーム 5-SECTION BOOM						
Travel	Travel FAIR · Attn				「オーバーヒートしやすい」記載あり NOTE ON "EASY TO OVERHEAT"						
воом					右Rアウトリガー外れあり REAR RIGHT OUTRIGGER: COME OFF						
MAIN BOOM				左Rアウトリガーシリンダー、ホース油漏れあり							
BOOM TOTAL				REAR LEFT OUTRIGGER CYLINDER & HOSE: OIL LEAKING							
•					左Fアウトリガーホース周り油漏れ小						
TOP SHEAVE YES . NO					AROUND FRO	AROUND FRONT LEFT OUTRIGGER CYLINDER HOSE: OIL LEAKING					
JIB					作動油タンク	作動油タンク上油漏れ小					
					UPPER PART OF HYDRAULIC OIL TANK: OIL LEAKING						
TOWER											

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)