

DUMP TRUCK ダンプ

INSPECTION DATE		2025/8/26	CATEGORY	ON-ROAD DUMP	OFF-ROAD DUMP
MAKE	KOMATSU			MODEL	HD465-7
SERIAL	7378			STAMP	7378
HR METER	UNKNOWN		HR	ODOMETER	10356 km
TIRE SIZE	24.00R35			YEAR	2005 YR

ENGINE : MODEL		6D170E-3		S/N		312274	
Oil leakage	FAIR	Attn					
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE				
Sound	FAIR	Attn					
Oil	FAIR	Attn					
Exhaust Color	FAIR	Attn					
US EPA	YES	NO					
OPERATION PUMP							
Sound	FAIR	Attn					
Oil leakage	FAIR	Attn	油漏れ小 OIL LEAKING				
Power	FAIR	Attn					
COOLING SYSTEM							
Radiator	FAIR	Attn					
Oil Cooler	FAIR	Attn					
TRANSMISSION & TRAVEL							
T/M TYPE	AT	MT			No. OF GEARS	6 GEARS	
Transmission	FAIR	Attn					
4WD	4WD	2WD					
Travel	FAIR	Attn					
Articulate	FAIR	Attn					
FOOT BRAKE	FAIR	Attn					
PARKING BRAKE	FAIR	Attn					
INTERIOR See Photos. 写真参照							
INTERIOR COND.	CLEAN · FAIR · DIRTY						
Operator's Seat	FAIR	Attn	破れあり MUCH WORN				
Glasses	FAIR	Attn					
AirCon	A/C	H/C · H only · C only · None					

MAIN FRAME					
MAIN FLAME		(FAIR)	▪	Attn	
VESSEL					
MAKE					
VESSEL		(FAIR)	▪	Attn	
REAR GATE TYPE		NORMAL		▪	L-GATE (FLAT)
REAR GATE		FAIR	▪	Attn	
UNDERCARRIAGE: See Photos. 写真参照					
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4
TIRE WEAR		FAIR ▪ WORN ▪ UNEVEN WEAR			
COMMENT					
ROPS CAB					
ベッセル内部材あり SOME PARTS: PUTTING IN VESSEL					
OIL LEAKING FROM LIFT CYLINDER WILL BE FIXED AFTER AUCTION					
左側ダンブシリンダー油漏れ大(オークション後修理してから出荷予定)					
LEFT DUMP CYLINDER: SEVERE OIL LEAKING (REPAIRING AFTER THE AUCTION) 					
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。