

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/8/25	MAKE	KUBOTA	MODEL	KH60
SERIAL	107-20096		STAMP	107-20096	
HR METER	4585	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		S/N
Oil leakage	FAIR ・ Attn	*1
Blow-By	FAIR ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE
Sound	FAIR ・ Attn	
Oil	FAIR ・ Attn	
Exhaust Color	FAIR ・ Attn	
US EPA	YES ・ NO	
MAIN PUMP		
Sound	FAIR ・ Attn	
Oil leakage	FAIR ・ Attn	にじみあり OIL OOZING
Power	FAIR ・ Attn	
COOLING SYSTEM		
Radiator	FAIR ・ Attn	
Oil Cooler	FAIR ・ Attn	
OPERATING SYSTEM		
Swing	FAIR ・ Attn	*2
Travel	FAIR ・ Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ・ FAIR ・	DIRTY
Operator's Seat	FAIR ・ Attn	
Glasses	FAIR ・ Attn	F割れあり UPPER WINDSHIELD: CRACKED
AirCon	A/C ・ H/C ・ H only ・ C only ・ None	
BOOM / ARM / BKT		
Boom	FAIR ・ Attn	
Boom Cylinder	FAIR ・ Attn	にじみあり OIL OOZING
Arm	FAIR ・ Attn	へコミあり DENT
Arm Cylinder	FAIR ・ Attn	
ATTACHMENT	FAIR ・ Attn	
BKT Cylinder	FAIR ・ Attn	

UNDERCARRIAGE :						See Photos.	写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)							3
COMMENT							
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()						
Lever	(LONG) • WRIST						
Multi	MULTI • 2 • NO						
ARM-CRANE	YES • NO						
BLADE	YES • NO						
OFFSET	YES • NO						
OFFSET Cylinder	FAIR • Attn						
Piping	(YES) • NO	(Breaker only) • Multi					
COMMENT							
ブーム背面ホースひび割れあり							
SOME HOSES AROUND LOWER PART OF BOOM: CRACKED							
*1 インジェクター周り油漏れあり、油污れ大							
*1 AROUND FUEL INJECTOR: OIL LEAKING, MUCH OIL STAINS							
*2 ゴリゴリ感あり、ガタ大 RATTLING, SWING: MUCH LOOSE							
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)							
							3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。