

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/9/16	MAKE	HITACHI	MODEL	LX100-5
SERIAL	41HP003105 / DWL10HD567183			STAMP	L100H-567183
HR METER	8182	HR	Odometer	54817	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	17.5-25 12PR (SNOW)

ENGINE : MODEL S/N T06068T760937

Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO

OPERATION PUMP

Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn

COOLING SYSTEM

Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn

TRANSMISSION & TRAVEL

T/M TYPE	PS	DD
Transmission	FAIR	Attn
Travel	FAIR	Attn
FOOT BRAKE	FAIR	Attn
PARKING BRAKE	FAIR	Attn

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	穴、汚れあり HOLES, DIRTY
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only C only None

FRONT & CYLINDERS

Arm	FAIR	Attn	左右シリンダーにじみあり CYLINDERS: OIL OOZING
Bell crank	FAIR	Attn	
Bucket	FAIR	Attn	シリンダーにじみあり CYLINDER: OIL OOZING
Articulate	FAIR	Attn	左右シリンダーにじみあり CYLINDERS: OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR (FAIR • WORN • UNEVEN WEAR)	

COMMENT

タコメーター TACHOMETER: 42365km

STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING

RIDE CONTROL YES NO

ATTACHMENTS

STD BKT	YES	OTHER	マルチプラウ MULTI PLOW
BLADE	YES	NO	Piping for Tilt YES NO

COMMENT

機体外装リペイントあり REPAINTED
マルチプラウクラックあり、右側底面ソリ欠
MULTI PLOW: CRACKED, RIGHT SLED: MISSING
A/Cぬるい A/C: MALFUNCTION
ラジオ故障あり RADIO: MALFUNCTION

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。