

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/10/10	MAKE	KOBELCO	MODEL	RK250-3
SERIAL No.	PLATE : NO PLATE			STAMP : EZ3-6199	
HR METER	12785	HR	Odometer	29523	km
TIRE SIZE	445/95R25			YEAR	YR

ENGINE : MODEL		S/N
Oil leakage	FAIR ☒ Attn	油漏れあり OIL LEAKING
Blow-By	FAIR ☒ Attn	A LITTLE ☒ MIDDLE ☐ SEVERE
Sound	FAIR ☐ Attn	
Oil	FAIR ☐ Attn	
Exhaust Color	FAIR ☐ Attn	

OPERATION PUMP		
Sound	FAIR ☐ Attn	
Oil leakage	FAIR ☐ Attn	
Power	FAIR ☐ Attn	

COOLING SYSTEM		
Radiator	FAIR ☐ Attn	
Oil Cooler	FAIR ☐ Attn	

OPERATING SYSTEM		
Computer	OK ☒ NG	
Swing	FAIR ☐ Attn	旋回位置不良 SWING POSITION SENSOR: MALFUNCTION
Travel	FAIR ☐ Attn	

TRANSMISSION		
Transmission	FAIR ☐ Attn	トルコン油漏れあり TORQUE CONVERTER: OIL LEAKING
No. OF GEARS	3 GEARS	
4WD	4WD ☐ 6WD	

INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN ☐ FAIR ☒ DIRTY	
Operator's Seat	FAIR ☐ Attn	
Glasses	FAIR ☐ Attn	
AirCon	A/C ☒ H/C ☐ H only ☐ C only ☐ None	

COMMENT		
各部へコミあり BODY: A LITTLE DEFORMED		
PTOスイッチ別にある W/ANOTHER PTO SWITCH		
エアー漏れあり AIR LEAKING		

BOOM		
No. of Section	4 SECTIONS	
CRACK/ENFORCEMENT	FAIR ☐ Attn	未確認 NOT CHECKED
DERRICKING CYL.	FAIR ☐ Attn	自然降下大 MUCH HYDRAULIC DRIFT
EXTENSION CYL.	FAIR ☐ Attn	油漏れあり OIL LEAKING
JIB	YES ☐ NO ☒	
JIB TYPE	STD ☐ PWR	
MAIN & SUB WIRE	YES ☐ NO ☒ *1	
FREE FALL	YES ☐ NO ☒	
HOOK	25t, BALL	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)		2
TIRE WEAR	FAIR ☒ WORN ☐ UNEVEN WEAR	

COMMENT		
旋回ロックピン操作レバー欠、ロック抜けない		
SWING LOCK LEVER: MISSING (LOCK: PIN: UNABLE TO RELEASE)		

OUTRIGGERS		
OUTRIGGERS	X ☒ H	
OUTRIGGERS COND.	FAIR ☐ Attn	*2
Oil leakage (JACK CYL.)	FRONT L ☐ R REAR L ☐ R	
Oil leakage (SLIDE CYL.)	FRONT L ☐ R REAR L ☐ R	

COMMENT		
ブーム引き出しシーブブラケット亀裂あり、伸縮操作未確認		
BOOM EXTENSION SHEAVE BRACKET: CRACKED,		
BOOM: NOT CHECKED TO TELESCOPE		
*1 主巻・補巻操作レバーガタ大(乱巻き注意)、主巻過巻S/W不良		
*1 OPERATION LEVERS: MUCH LOOSE (NEED TO BE CAREFUL IN IRREGULAR WINDING),		
MAIN WIRE OVERWINDING PREVENTION SWITCH: MALFUNCTION		
*2 左F縦シリンダーロッド傷、にじみあり FRONT LEFT VERTICAL CYLINDER ROD: SCRATCHED, OIL OOOZING		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。