

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/1/20	MAKE	TADANO	MODEL	TR-500M-2
SERIAL No.	PLATE : 581282		STAMP : TR550-1282		
HR METER	677	HR	Odometer	18351	km
TIRE SIZE	505/95R25		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Computer	☒ OK · NG	
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
TRANSMISSION		
Transmission	☒ FAIR · Attn	
No. OF GEARS	3	GEARS
4WD	☒ 4WD · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · ☒ FAIR ·	DIRTY
Operator's Seat	☒ FAIR · Attn	穴あり HOLES
Glasses	☒ FAIR · Attn	
AirCon	☒ A/C · H/C · H only · C only · None	
COMMENT		

BOOM			
No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	☒ FAIR · Attn		
DERRICKING CYL.	☒ FAIR · Attn		
EXTENSION CYL.	☒ FAIR · Attn		
JIB	☒ YES · NO		
JIB TYPE	STD · ☒ PWR		
MAIN & SUB WIRE	☒ YES · NO		
FREE FALL	☒ YES · NO		
HOOK	45t, 25t, BALL		
UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)			3
TIRE WEAR ☒ FAIR · ☐ WORN · ☐ UNEVEN WEAR			
COMMENT			
右Fタイヤ側面ひび割れあり FRONT RIGHT TIRE SIDEWALL: CRACKED			
OUTRIGGERS			
OUTRIGGERS	X · ☒ H		
OUTRIGGERS COND.	FAIR · ☒ Attn	*1	
Oil leakage (JACK CYL.)	FRONT ☒ L · R	REAR ☒ L · R	
Oil leakage (SLIDE CYL.)	FRONT L · R	REAR L · R	
COMMENT			
E/Gストップ不良 ENGINE STOPPER: MALFUNCTION			
*1 右F縦シリンダーロッド傷あり FRONT RIGHT JACK CYLINDER: SCRATCHED			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。