

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/27	MAKE	KOMATSU	MODEL	PC220LC-8N0
SERIAL	75227		STAMP	KMTPC181K02075227	
HR METER	16228	HR	YEAR	2007	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700G	

ENGINE :		MODEL	6D107E-1	S/N	26776390
Oil leakage	FAIR	Attn			
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR	Attn			
Oil	FAIR	Attn			
Exhaust Color	FAIR	Attn			
US EPA	YES	NO			
MAIN PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
OPERATING SYSTEM					
Swing	FAIR	Attn			
Travel	FAIR	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN · FAIR · DIRTY				
Operator's Seat	FAIR	Attn	*1		
Glasses	FAIR	Attn			
AirCon	A/C · H/C · H only · C only · None				
BOOM / ARM / BKT					
Boom	FAIR	Attn			
Boom Cylinder	FAIR	Attn			
Arm	FAIR	Attn			
Arm Cylinder	FAIR	Attn			
ATTACHMENT	FAIR	Attn			
BKT Cylinder	FAIR	Attn	傷あり SCRATCHED		

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3				
COMMENT					
左Fキャリアローラー偏摩耗あり FRONT LEFT CARRIER ROLLER: UNEVEN WEARING					
BKT	STD / SLOPE / NARROW / SKELETON OTHER(MAGNET)				
Lever	LONG	WRIST			
Multi	MULTI	2 NO			
ARM-CRANE	YES	NO			
BLADE	YES	NO			
OFFSET	YES	NO			
OFFSET Cylinder	FAIR	Attn			
Piping	YES	NO	Breaker only	Multi	5
COMMENT					
エレベータCAB ELEVATOR CAB E15表示あり “E15” ERROR DISPLAY *1 ヘッドレスト欠、破れあり HEADREST: MISSING, HUGE CUT					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。