

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/10/28	MAKE	KOMATSU	MODEL	LT300-1
SERIAL No.	PLATE : 20091		STAMP : L002-20091		
HR METER	7914	HR	Odometer	61236	km
TIRE SIZE	295/80R22.5		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
OPERATION PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Computer	OK · NG	未確認 NOT CHECKED
Swing	FAIR · Attn	
Travel	FAIR · Attn	
TRANSMISSION		
Transmission	FAIR · Attn	
No. OF GEARS	3	GEARS
4WD	4WD · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
COMMENT		

BOOM					
No. of Section		6		SECTIONS	
CRACK/ENFORCEMENT		FAIR	Attn	未確認 NOT CHECKED	
DERRICKING CYL.		FAIR	Attn		
EXTENSION CYL.		FAIR	Attn		
JIB		YES	NO		
JIB TYPE		STD	PWR		
MAIN & SUB WIRE		YES	NO		
FREE FALL		YES	NO		
HOOK		4.9t, BALL			
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)					2
TIRE WEAR		FAIR WORN UNEVEN WEAR			
COMMENT					
OUTRIGGERS					
OUTRIGGERS		X	H		
OUTRIGGERS COND.		FAIR	Attn		
Oil leakage (JACK CYL.)	FRONT	L	R	REAR	L R
Oil leakage (SLIDE CYL.)	FRONT	L	R	REAR	L R
COMMENT					
クレーン操作未確認 CRANE OPERATION: NOT CHECKED					
エアー漏れあり AIR LEAKING					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。