

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/11/27	MAKE	KOMATSU	MODEL	D20PLL-7
SERIAL	62009			STAMP	D20PL7-62009
HR METER	5335	HR	SHOE	1050LGP	YEAR YR
BLADE	STRAIGHT (ST/TILT) PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL 3TN86L S/N 03917	
Oil leakage	FAIR • (Attn) *1
Blow-By	(FAIR) • Attn A LITTLE • MIDDLE • SEVERE
Sound	(FAIR) • Attn
Oil	(FAIR) • Attn
Exhaust Color	(FAIR) • Attn
US EPA	YES • (NO)
OPERATION PUMP	
Sound	(FAIR) • Attn
Oil leakage	(FAIR) • Attn
Power	(FAIR) • Attn
COOLING SYSTEM	
Radiator	(FAIR) • Attn
Oil Cooler	(FAIR) • Attn
TRANSMISSION & TRAVEL	
T/M TYPE	PS • (DD) DIFF. STEERING YES • (NO)
Transmission	(FAIR) • Attn
Travel	FAIR • (Attn) *2
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • FAIR • (DIRTY)
Operator's Seat	(FAIR) • Attn
Glasses	(FAIR) • Attn
AirCon	A/C • H/C • (H only) • C only • None
BLADE & CYLINDERS	
BLADE	(FAIR) • Attn
CYLD.(R)	(FAIR) • Attn
CYLD.(L)	(FAIR) • Attn
TILT CYLD	(FAIR) • Attn
ANGLE CYLD	FAIR • Attn

UNDERCARRIAGE See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	
COMMENT	
Ripper MULTI • S/S Shanks PCS	
Ripper CYLD. FAIR • Attn	
COMMENT	
機体外装リペイントあり REPAINTED	
ラジオ故障あり RADIO: MALFUNCTION	
マフラー下部パイプ外れのためにじみ、 エキゾーストマニホールド上にあるためにじみ垂れあり	
LOWER PIPE OF MUFFLER: NOT CONNECTING, OIL OOZING, OIL DRIPPING TO THE EXHAUST MANIFOLD	
下周りにじみあり BOTTOM: OIL OOZING	
*1 E/G上部周りにじみあり AROUND UPPER PART OF ENGINE: OIL OOZING	
*2 右側走行反応遅い RIGHT TRACK: DULL MOVING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。