

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/12/23	MAKE	KATO	MODEL	KR-70H-LM
SERIAL No.	PLATE : 5210194			STAMP : UNREADABLE	
HR METER	ERROR		HR	Odometer	ERROR km
TIRE SIZE	385/95R25			YEAR	YR

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	オイルパン付近油漏れ小 AROUND OIL PAN: OIL LEAKING
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	

OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	

COOLING SYSTEM		
Radiator	☒ FAIR · Attn	F90、F96エラー表示あり "F90" & "F96 ERRORS DISPLAY
Oil Cooler	☒ FAIR · Attn	

OPERATING SYSTEM		
Computer	☒ OK · NG	
Swing	☒ FAIR · Attn	旋回ロック不良 SWING LOCK: MALFUNCTION
Travel	☒ FAIR · Attn	自走不可 UNABLE TO RUN ON PUBLIC ROADS

TRANSMISSION		
Transmission	☒ FAIR · Attn	
No. OF GEARS	4 GEARS	
4WD	☒ 4WD · 6WD	

INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY	
Operator's Seat	☒ FAIR · Attn	
Glasses	☒ FAIR · Attn	
AirCon	☒ A/C · H/C · H only · C only · None	

COMMENT	
右前1軸、左前2軸ステアリングシリンダー油漏れあり	
FRONT TEST RIGHT & 2nd FRONT LEFT STEERING CYLINDERS: OIL LEAKING	
伸縮レバー固着あり EXTENSION LEVER: STUCK	

BOOM		
No. of Section	6 SECTIONS	
CRACK/ENFORCEMENT	☒ FAIR · ☒ Attn	補修あり REPAIRED
DERRICKING CYL.	☒ FAIR · Attn	
EXTENSION CYL.	☒ FAIR · Attn	
JIB	☒ YES · NO	*1
JIB TYPE	STD · ☒ PWR	
MAIN & SUB WIRE	☒ YES · NO	
FREE FALL	YES · ☒ NO	
HOOK	60t, 25t, BALL	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)		1
TIRE WEAR	☒ FAIR · WORN · UNEVEN WEAR	

COMMENT	
リヤステロック不良 REAR STEERING LOCK: MALFUNCTION	
左前配管油漏れ大 SOME FRONT LEFT PIPE OF BOTTOM: SEVERE OIL LEAKING	

OUTRIGGERS					
OUTRIGGERS	X · ☒ H				
OUTRIGGERS COND.	☒ FAIR · ☒ Attn	*2			
Oil leakage (JACK CYL.)	FRONT ☒ L · R	REAR	L ☒ R		
Oil leakage (SLIDE CYL.)	FRONT L · R	REAR	L · R		

COMMENT	
クレーン操作時伸縮動作止まる	
CRANE: STOPPING TO TELESCOPE WHEN OPERATING CRANE	
伸縮ホース付近油漏れあり AROUND EXTENSION CYLINDER HOSE: OIL LEAKING	
*1 油圧ホース欠品、ジブ取付部溶接修理あり、ジブコードリール不良	
*1 HOSE: MISSING, ATTACHING PART: WELDED, CORD REEL: MALFUNCTION	
*2 左右F、右R縦シリンダーロッド傷あり	
*2 REAR RIGHT & FRONT JACK CYLINDER: SCRATCHED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。