

DUMP TRUCK ダンプ

INSPECTION DATE		2026/1/23	CATEGORY	ON-ROAD DUMP	OFF-ROAD DUMP
MAKE	KOMATSU			MODEL	HM300-2
SERIAL	2575			STAMP	KMTHM005J26002575
HR METER	13108	HR	ODOMETER	75669	km
TIRE SIZE	30/65R25			YEAR	YR

ENGINE : MODEL		6D125E-5		S/N		564403	
Oil leakage	FAIR	Attn					
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE				
Sound	FAIR	Attn					
Oil	FAIR	Attn					
Exhaust Color	FAIR	Attn					
US EPA	YES	NO					
OPERATION PUMP							
Sound	FAIR	Attn					
Oil leakage	FAIR	Attn					
Power	FAIR	Attn					
COOLING SYSTEM							
Radiator	FAIR	Attn					
Oil Cooler	FAIR	Attn					
TRANSMISSION & TRAVEL							
T/M TYPE	AT	MT			No. OF GEARS	5 GEARS	
Transmission	FAIR	Attn					
4WD	4WD	2WD					
Travel	FAIR	Attn					
Articulate	FAIR	Attn					
FOOT BRAKE	FAIR	Attn					
PARKING BRAKE	FAIR	Attn					
INTERIOR See Photos. 写真参照							
INTERIOR COND.	CLEAN	FAIR	DIRTY				
Operator's Seat	FAIR	Attn	穴あり HOLES				
Glasses	FAIR	Attn					
AirCon	A/C	H/C	H only	C only	None		

MAIN FRAME					
MAIN FLAME		FAIR	▪	Attn	
VESSEL					
MAKE		-			
VESSEL		FAIR	▪	Attn	*1
REAR GATE TYPE		NORMAL		▪	L-GATE (FLAT)
REAR GATE		FAIR	▪	Attn	
UNDERCARRIAGE: See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
TIRE WEAR		FAIR • WORN • UNEVEN WEAR			
COMMENT					
下周り油漏れあり BOTTOM: OIL LEAKING					
中折れ周りホース破れあり					
SOME HOSES AROUND ARTICULATE PART: A LITTLE DAMAGED					
ROPS-CAB					
前後ギア入れると(N以外に入れると)！マーク表示、ブザー音あり					
WARNING LAMP & WARNING SOUNDS:					
ON WHEN SHIFTING IN DRIVE or REVERSE GEAR					
(EXCEPT NEUTRAL GEAR)					
*1 右側リフトシリンダー油漏れ、左側にじみあり					
*1 RIGHT LIFT CYLINDER: OIL LEAKING, LEFT LIFT CYLINDER: OIL OOZING					
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。