

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/1/22	MAKE	TADANO	MODEL	TR-160M-3
SERIAL No.	PLATE :	525641	STAMP :	TR162-0265	
HR METER	1984	HR	Odometer	1140	km
TIRE SIZE	325/95R24	YEAR	YR		

ENGINE : MODEL		S/N
Oil leakage	FAIR <input type="radio"/> Attn	E/G下部油漏れあり BOTTOM OF ENGINE: OIL LEAKING
Blow-By	FAIR <input type="radio"/> Attn	A LITTLE · MIDDLE · <b>SEVERE</b>
Sound	FAIR <input type="radio"/> Attn	
Oil	FAIR <input type="radio"/> Attn	
Exhaust Color	FAIR <input type="radio"/> Attn	白煙あり WHITE FUMES

OPERATION PUMP	
Sound	FAIR <input type="radio"/> Attn
Oil leakage	FAIR <input type="radio"/> Attn
Power	FAIR <input type="radio"/> Attn

COOLING SYSTEM	
Radiator	FAIR <input type="radio"/> Attn 内部サビあり INSIDE OF RADIATOR: RUSTY
Oil Cooler	FAIR <input type="radio"/> Attn

OPERATING SYSTEM	
Computer	OK <input type="radio"/> NG
Swing	FAIR <input type="radio"/> Attn 未確認 NOT CHECKED
Travel	FAIR <input type="radio"/> Attn 自走不可 UNABLE TO RUN ON PUBLIC ROADS

TRANSMISSION	
Transmission	FAIR <input type="radio"/> Attn *1
No. OF GEARS	4 GEARS
4WD	4WD <input type="radio"/> 6WD

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · <b>DIRTY</b>
Operator's Seat	FAIR <input type="radio"/> Attn
Glasses	FAIR <input type="radio"/> Attn
AirCon	A/C <input type="radio"/> H/C · H only · C only · None

COMMENT	
ブーム伸縮不良(未確認)	
BOOM: MALFUNCTION TO TELESCOPE (OPERATION: NOT CHECKED)	
マフラーテールパイプ欠品 MUFFLER TAILPIPE: MISSING	

BOOM	
No. of Section	6 SECTIONS
CRACK/ENFORCEMENT	FAIR <input type="radio"/> Attn
DERRICKING CYL.	FAIR <input type="radio"/> Attn
EXTENSION CYL.	FAIR <input type="radio"/> Attn 未確認 NOT CHECKED
JIB	YES <input type="radio"/> NO <input checked="" type="radio"/>
JIB TYPE	STD <input type="radio"/> PWR
MAIN & SUB WIRE	YES <input type="radio"/> NO *2
FREE FALL	YES <input type="radio"/> NO
HOOK	16t, BALL

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)	3
TIRE WEAR	FAIR <input type="radio"/> <b>WORN</b> · UNEVEN WEAR

COMMENT	
リアステアリング不良 REAR STEERING: MALFUNCTION	
右前タイヤサイド亀裂あり FRONT RIGHT TIRE SIDEWALL: MUCH CRACKED	

OUTRIGGERS	
OUTRIGGERS	X <input type="radio"/> H *3
OUTRIGGERS COND.	FAIR <input type="radio"/> Attn
Oil leakage (JACK CYL.)	FRONT L · R REAR L · R
Oil leakage (SLIDE CYL.)	FRONT L · R REAR L · R

COMMENT	
主・補巻過巻装置なし、過巻不良	
OVERWINDING PREVENTION DEVICE: NOTHING, OVERWINDING PREVENTION: MALFUNCTION	
コントロールバルブ付近油圧配管油漏れあり	
SOME PIPE AROUND CONTROL VALVE: OIL LEAKING	
*1 ミッションゲージ油漏れあり TRANSMISSION OIL LEVEL GAUGE: OIL LEAKING	
*2 主・補巻乱巻あり MAIN & AUXILIARY HOISTING WIRES: IRREGULAR WINDING	
*3 外からしか操作できない ONLY ABLE TO OPERATE FROM OUTSIDE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。