

INSPECTION SHEET 検品書
EXCAVATOR バックホー

| | | | | | |
|-----------------|---|------|---------|-------------|-----------|
| INSPECTION DATE | 2026/1/20 | MAKE | KOMATSU | MODEL | PC400LC-6 |
| SERIAL | 30361 | | STAMP | PC400-30361 | |
| HR METER | 11155 | HR | YEAR | 1997 | YR |
| CAB/CNP | ROPS CAB <input checked="" type="checkbox"/> CAB <input type="checkbox"/> ROPS CNP / CNP / NONE | | SHOE | 700G | |

| ENGINE : MODEL S/N | | | UNDERCARRIAGE : See Photos. 写真参照 | | | | |
|---------------------------|---|-------------------------------|--|--|--|--|--|
| Oil leakage | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *1 | | RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 | | | |
| Blow-By | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> A LITTLE <input checked="" type="checkbox"/> MIDDLE <input type="checkbox"/> SEVERE | | COMMENT | | | | |
| Sound | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *1 | | スイベル下周り油漏れあり BOTTOM OF SWIVEL: OIL LEAKING | | | | |
| Oil | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *1 | | トラックフレームリペイントあり TRACK FRAMES: REPAINTED | | | | |
| Exhaust Color | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *1 | | 旋回モーター油漏れあり SWING MOTOR: OIL LEAKING | | | | |
| US EPA | YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> *1 | | ブーム背面ホースひび割れあり SOME HOSES AROUND BOOM: MUCH CRACKED | | | | |
| MAIN PUMP | | | BKT | STD <input type="checkbox"/> SLOPE <input type="checkbox"/> NARROW <input type="checkbox"/> SKELETON <input type="checkbox"/> OTHER() | | | |
| Sound | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *1 | | Lever | LONG <input type="checkbox"/> WRIST <input checked="" type="checkbox"/> *1 | | | |
| Oil leakage | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *1 | 油漏れあり OIL LEAKING | Multi | MULTI <input type="checkbox"/> 2 <input checked="" type="checkbox"/> NO | | | |
| Power | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *1 | | ARM-CRANE | YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> *1 | | | |
| COOLING SYSTEM | | | BLADE | YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> *1 | | | |
| Radiator | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *1 | 冷却水:油混じりあり OIL: MIXED | OFFSET | YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> *1 | | | |
| Oil Cooler | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *1 | | OFFSET Cylinder | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *1 | | | |
| OPERATING SYSTEM | | | Piping | YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> *1 Breaker only <input type="checkbox"/> Multi | | | |
| Swing | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *1 | ガタあり SWING: LOOSE | COMMENT | | | | |
| Travel | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *1 | | 右側底板欠 SOME RIGHT UNDER COVERS: MISSING | | | | |
| INTERIOR See Photos. 写真参照 | | | 底板周り油漏れあり BOTTOM: OIL LEAKING | | | | |
| INTERIOR COND. | CLEAN <input type="checkbox"/> FAIR <input checked="" type="checkbox"/> *1 DIRTY <input type="checkbox"/> *1 | | ブーム付根フレーム側パッチあり | | | | |
| Operator's Seat | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *1 | | FRAME SIDE OF ATTACHING PART OF BOOM: PATCHED | | | | |
| Glasses | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *1 | | 右サイドカバーラッチ掛からない RIGHT SIDE COVER LATCH: NOT WORKING | | | | |
| AirCon | A/C <input type="checkbox"/> H/C <input type="checkbox"/> H only <input type="checkbox"/> C only <input type="checkbox"/> None <input checked="" type="checkbox"/> *1 | | 油圧掛けるとE/G回転数落ちる | | | | |
| BOOM / ARM / BKT | | | ENGINE SPEED: GOING DOWN DURING SUPPLYING SOME HYDRAULIC PRESSURE | | | | |
| Boom | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *2 | | *1 ヘッド周り油漏れあり AROUND CYLINDER HEAD: OIL LEAKING | | | | |
| Boom Cylinder | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *2 | 左右にじみあり CYLINDERS: OIL Oozing | *2 18.6mスーパーロング、パッチ補修跡、ガタあり | | | | |
| Arm | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *3 | | *2 18.6m SUPER LONG, REPAIRED, LOOSE | | | | |
| Arm Cylinder | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *3 | にじみあり OIL Oozing | *3 パッチ補修跡、ガタ、クラックあり REPAIRED, LOOSE, CRACKED | | | | |
| ATTACHMENT | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *4 | | *4 パケットピン周りボルト欠、ガタあり SOME PIN LOCK BOLTS: MISSING, LOOSE | | | | |
| BKT Cylinder | FAIR <input type="checkbox"/> Attn <input checked="" type="checkbox"/> *4 | | RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | | | |
| | | | | 3 | | | |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。