

OTHER その他

| | | | |
|-----------|------|--------|--|
| CONDITION | FAIR | ▪ Attn | |
| | | | |

| | | | | | |
|---|---|-----------|---------------------------|--|--|
| UNDERCARRIAGE : See Photos. 写真参照 | | | | | |
| RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 3 | TIRE WEAR | FAIR ・ WORN ・ UNEVEN WEAR | | |
| COMMENT コンベア右側傾斜シリンダーにじみあり RIGHT INCLINE ADJUSTMENT CYLINDER OF CONVEYOR: OIL OOZING コンベア折畳みシリンダーメッキ剥がれあり CONVEYOR EXTENSION CYLINDER: COATING PEELED 走行リモコンあり(本体の中) REMOTE CONTROL FOR TRAVELING: BEING IN BODY | | | | | |
| RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | | 3 | | | |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。