

INSPECTION SHEET 検品書
WHEEL EXCAVATOR タイヤバックホー

INSPECTION DATE	2026/1/26	MAKE	HITACHI	MODEL	ZX400W-3		
SERIAL	HCMCSF00J00058593			STAMP	HCMCSF00J00058593		
HR METER	22074	HR	Odometer	—	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	16.00-25		

ENGINE : MODEL		6HK1	S/N
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	

MAIN PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	油漏れあり OIL LEAKING
Power	FAIR	Attn	

COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

OPERATING SYSTEM			
Swing	FAIR	Attn	ガタあり SWING: LOOSE
Travel	FAIR	Attn	

INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	穴あり HOLES
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None

BOOM / ARM / BKT			
Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	ガタあり LOOSE
Arm Cylinder	FAIR	Attn	
ATTACHMENT	FAIR	Attn	*1
BKT Cylinder	FAIR	Attn	メッキ剥がれあり COATING: PEELED

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR

COMMENT	
スイベル周り油漏れあり AROUND SWIVEL: OIL LEAKING	
左右ステアリングシリンダーにじみあり STEERING CYLINDERS: OIL OozING	
左右Fダンパーシリンダーにじみあり FRONT DAMPER CYLINDERS: OIL OozING	

BKT	STD / SLOPE / NARROW / SKELETON	OTHER (MAGNET)
Lever	LONG	WRIST
Multi	MULTI · 2	NO
ARM-CRANE	YES	NO
BLADE	YES	NO
OFFSET	YES	NO
OFFSET Cylinder	FAIR	Attn
Piping	YES	NO Breaker only · Multi
OUTRIGGERS COND.	FAIR	Attn *2

COMMENT	
ブーム背面ホース油漏れあり SOME HOSE AROUND BOOM: OIL LEAKING	
エレベータCAB: 左右シリンダー油漏れあり ELEVATOR CAB (CYLINDERS: OIL LEAKING)	
ミッション油漏れあり TRANSMISSION: OIL LEAKING	
バックカメラ不良 BACK MONITOR: MALFUNCTION	
本体ステップあり W/SIDE STEP	
*1 動作音するが吸着しない NOT ATTRACTING (JUST WORKING SOUNDS)	
*2 左Rシリンダー傷あり REAR LEFT CYLINDER: SCRATCHED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。