

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

INSPECTION DATE	2026/4/13	MAKE	CAT	MODEL	349EL
SERIAL	CAT0349EPSPG00249		STAMP	CAT0349EPSPG00249	
HR METER	8491 / 8496	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

<b>ENGINE : MODEL</b> C13 <b>S/N</b> TXM06648	
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · <b>NO</b>
<b>MAIN PUMP</b>	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · <b>Attn</b> *1
<b>COOLING SYSTEM</b>	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
<b>OPERATING SYSTEM</b>	
Swing	FAIR · Attn
Travel	FAIR · <b>Attn</b> *2
<b>INTERIOR See Photos. 写真参照</b>	
INTERIOR COND.	CLEAN · <b>FAIR</b> · DIRTY
Operator's Seat	FAIR · Attn 破れあり MUCH WORN
Glasses	FAIR · <b>Attn</b> *3
AirCon	<b>A/C</b> · H/C · H only · C only · None
<b>BOOM / ARM / BKT</b>	
Boom	FAIR · Attn
Boom Cylinder	FAIR · <b>Attn</b> 左右油漏れあり CYLINDERS: OIL LEAKING
Arm	FAIR · Attn ガタあり LOOSE
Arm Cylinder	FAIR · Attn
ATTACHMENT	FAIR · Attn
BKT Cylinder	FAIR · <b>Attn</b> *4

<b>UNDERCARRIAGE : See Photos. 写真参照</b>	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
<b>COMMENT</b>	
底板油汚れあり BOTTOM: OIL STAINS	
ポンプ下配管油漏れ小 SOME PIPE UNDER PUMP: OIL LEAKING	
バックカメラ表示不良 BACK MONITOR: MALFUNCTION	
ポンプ不良 PUMP: MALFUNCTION	
BKT	<b>STD</b> / SLOPE / NARROW / SKELETON / OTHER ( )
Lever	LONG · <b>WRIST</b>
Multi	MULTI · 2 · <b>NO</b>
ARM-CRANE	YES · <b>NO</b>
BLADE	YES · <b>NO</b>
OFFSET	YES · <b>NO</b>
OFFSET Cylinder	FAIR · Attn
Piping	<b>YES</b> · NO <b>Breaker only</b> · Multi
<b>COMMENT</b>	
*1 パワー弱い、ブームで車体上がらない	
*1 WEAK POWER, UNABLE TO PUSH UP THE BODY BY BOOM	
*2 右足動作しない	
(左レバーを入れながら左右走行レバーを倒せば前後進可能、右足のみでの走行不可、左足は問題なし)	
*2 RIGHT TRACK: NOT MOVING	
(ABLE TO TRAVEL WITH BOTH TRACKS	
DURING A LITTLE TILTING LEFT OPERATION LEVER FOR BUCKET)	
*3 ドア下アクリル、F割れあり	
*3 LOWER DOOR GLASS: ACRYLIC BOARD, WINDSHIELD: CRACKED	
*4 にじみ、不定期で動作しない時あり(左右走行レバーを少し倒しながら操作すると動く)	
*4 OIL Oozing, OFTEN NOT MOVING	
(ABLE TO OPERATE DURING A LITTLE TILTING TRAVEL LEVERS)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。