

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2026/6/10	MAKE	KOMATSU	MODEL	D20PL-5
SERIAL	50246		STAMP	20PL5-50246	
HR METER	2323	HR	SHOE	690LGP	YEAR YR
BLADE	STRAIGHT / <u>ST/TILT</u> / PAT / ANGLE / OTHER		CAB/CNP	ROPS CAB / CAB / ROPS <u>CNP</u> / CNP / NONE	

ENGINE : MODEL		S/N
Oil leakage	<u>FAIR</u> · Attn	
Blow-By	<u>FAIR</u> · Attn	A LITTLE · MIDDLE · SEVERE
Sound	<u>FAIR</u> · Attn	
Oil	<u>FAIR</u> · Attn	
Exhaust Color	<u>FAIR</u> · Attn	
US EPA	YES · <u>NO</u>	
OPERATION PUMP		
Sound	<u>FAIR</u> · Attn	
Oil leakage	<u>FAIR</u> · Attn	
Power	<u>FAIR</u> · Attn	
COOLING SYSTEM		
Radiator	<u>FAIR</u> · <u>Attn</u>	水漏れ小 COOLANT LEAKING
Oil Cooler	<u>FAIR</u> · Attn	
TRANSMISSION & TRAVEL		
T/M TYPE	<u>PS</u> · DD	DIFF. STEERING YES · <u>NO</u>
Transmission	<u>FAIR</u> · Attn	
Travel	<u>FAIR</u> · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · <u>FAIR</u> · DIRTY	
Operator's Seat	<u>FAIR</u> · Attn	
Glasses	<u>FAIR</u> · Attn	
AirCon	A/C · H/C · <u>H only</u> · C only · None	
BLADE & CYLINDERS		
BLADE	<u>FAIR</u> · Attn	
CYLD.(R)	<u>FAIR</u> · Attn	
CYLD.(L)	<u>FAIR</u> · Attn	
TILT CYLD	<u>FAIR</u> · Attn	ホース1本修理あり SOME HOSE: REPAIRED
ANGLE CYLD	<u>FAIR</u> · Attn	

UNDERCARRIAGE See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2
COMMENT			
Ripper	MULTI · S/S	Shanks	PCS
Ripper CYLD.	<u>FAIR</u> · Attn		
COMMENT			
E/Gストップ不良 ENGINE STOPPER: MALFUNCTION			
ペダル両方固着気味 PEDALS: A LITTLE STUCK			
E/G回転レバー固着あり ACCELERATOR LEVER: STUCK			
ヒーター使えない HEATER: NOT WORKING			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。