

INSPECTION SHEET 検品書

TRUCK CRANE / ALL TERRAIN CRANE トラッククレーン / オールテレーンクレーン

INSPECTION DATE	2026/6/9	CATEGORY	TRUCK CRANE / ALL TERRAIN CRANE			
MAKE	KATO		MODEL	NK-75M-V		
SERIAL	7120619		STAMP	FK4??E-????? SOME LETTERS: UNREADABLE		
HR METER	UNKNOWN	HR	Odometer	167118 km	YEAR	YR
CHASSIS	MODEL	U-FK415ED改	No.	540973	TIRE	225/90R17.5

ENGINE(CRANE) : MODEL		S/N	
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
ENGINE(CHASSIS) : MODEL		6D14	S/N
Oil leakage	FAIR · Attn	*1	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn	白煙大 MUCH WHITE FUMES	
OPERATION PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn	にじみあり OIL OOZING	
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Computer	OK · NG	画面映らない MONITOR: NOT DISPLAYING	
Swing	FAIR · Attn		
Travel	FAIR · Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	AT · MT	No. OF GEARS	5 GEARS
Transmission	FAIR · Attn		
No. of DRIVE WHEELS	2	WD	
Travel	FAIR · Attn		
FOOT BRAKE	FAIR · Attn		
PARKING BRAKE	FAIR · Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn	破れあり TORN	
Glasses	FAIR · Attn	*2	
AirCon	A/C · H/C · H only · C only · NONE		

CRANE	
WEIGHT	-
HOOK	4.9t, BALL
BOOM	
MAIN BOOM	
BOOM TOTAL	
No. of Section	4 SECTIONS
TOP SHEAVE	YES · NO
JIB	STD · PWR
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
左Rタイヤ側面ひび割れあり REAR LEFT TIRE SIDEWALL: CRACKED	
ボディへコミ箇所多数あり BODY: A LITTLE DEFORMED	
ボディ各部パテ、リペイントあり BODY: PUTTIED, REPAINTED	
OUTRIGGERS	
OUTRIGGERS	FAIR · Attn H-TYPE *3
FRONT JACK	YES · NO ロッドサビ大 RODS: MUCH RUSTY
COMMENT	
クレーンCAB損傷大、外からドア開かない、内張り剥がれあり	
CRANE CAB: A LITTLE DEFORMED,	
DOOR: UNABLE TO OPEN FROM OUTSIDE, INSIDE COVERS: PEELED OFF	
過巻配線断線あり OVERWINDING PREVENTION WIRING: DISCONNECTED	
*1 E/Gオイルエレメント下、ダイナモ付近油漏れあり	
*1 LOWER PART OF ENGINE OIL FILTER & AROUND DYNAMO: OIL LEAKING	
*2 クレーンCABスライドガラス1枚欠、もう1枚はアクリル板	
*2 SOME SLIDE GLASS OF CRANE CAB: MISSING,	
OTHER SLIDE GLASS: ACRYLIC BOARD	
*3 左右F縦シリンダー油漏れ(オークション後終了予定)、	
左R縦シリンダー油漏れあり、左FR縦シリンダー自然降下あり	
*3 FRONT JACK CYLINDERS: OIL LEAKING (REPAIRING AFTER THE AUCTION),	
REAR LEFT JACK CYLINDER: OIL LEAKING,	
LEFT JACK CYLINDERS: HYDRAULIC DRIFT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。