

INSPECTION SHEET 検品書  
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2026/6/12	MAKE	KATO	MODEL	KR-65H
SERIAL No.	PLATE :	0310208		STAMP :	KRC002-0208
HR METER	8219	HR	Odometer	114474	km
TIRE SIZE	505/95R25		YEAR	2006	YR

**ENGINE : MODEL S/N**

Oil leakage	FAIR	<input checked="" type="radio"/> Attn	下部にじみあり BOTTOM: OIL OOZING
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	

**OPERATION PUMP**

Sound	FAIR	<input checked="" type="radio"/> Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	

**COOLING SYSTEM**

Radiator	FAIR	<input checked="" type="radio"/> Attn	
Oil Cooler	FAIR	Attn	

**OPERATING SYSTEM**

Computer	OK	<input checked="" type="radio"/> NG	
Swing	FAIR	Attn	
Travel	FAIR	Attn	

**TRANSMISSION**

Transmission	FAIR	<input checked="" type="radio"/> Attn	*1
No. OF GEARS	4	GEARS	
4WD	<input checked="" type="radio"/>	<input type="radio"/> 6WD	

**INTERIOR See Photos. 写真参照**

INTERIOR COND.	CLEAN	<input checked="" type="radio"/> FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	<input checked="" type="radio"/> A/C	<input type="radio"/> H/C · <input type="radio"/> H only · <input type="radio"/> C only · <input type="radio"/> None	

**COMMENT**


**BOOM**

No. of Section	6	SECTIONS	
CRACK/ENFORCEMENT	FAIR	Attn	
DERRICKING CYL.	FAIR	Attn	
EXTENSION CYL.	FAIR	Attn	
JIB	<input checked="" type="radio"/> YES	<input type="radio"/> NO	
JIB TYPE	STD	<input checked="" type="radio"/> PWR	
MAIN & SUB WIRE	<input checked="" type="radio"/> YES	<input type="radio"/> NO	
FREE FALL	<input checked="" type="radio"/> YES	<input type="radio"/> NO	
HOOK	65t, 34t, BALL		

**UNDERCARRIAGE : See Photos. 写真参照**

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	<input checked="" type="radio"/> FAIR · <input type="radio"/> WORN · <input type="radio"/> UNEVEN WEAR

**COMMENT**


**OUTRIGGERS**

OUTRIGGERS	X	<input checked="" type="radio"/> H	
OUTRIGGERS COND.	FAIR	Attn	
Oil leakage (JACK CYL.)	FRONT	<input type="radio"/> L · <input type="radio"/> R	REAR <input type="radio"/> L · <input type="radio"/> R
Oil leakage (SLIDE CYL.)	FRONT	<input type="radio"/> L · <input type="radio"/> R	REAR <input type="radio"/> L · <input type="radio"/> R

**COMMENT**

*1 トルコン付近にじみあり AROUND TORQUE CONVERTER: OIL OOZING	

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。