

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2026/8/3	MAKE	MAEDA	MODEL	MC-264HCD
SERIAL No.	PLATE :	253009	STAMP	253009	
HR METER	UNKNOWN	HR	SHOE	180R	YEAR YR

ENGINE : MODEL		S/N
Oil leakage	FAIR • Attn	
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn	
Oil	FAIR • Attn	
Exhaust Color	FAIR • Attn	
OPERATION PUMP		
Sound	FAIR • Attn	
Oil leakage	FAIR • Attn	
Power	FAIR • Attn	
COOLING SYSTEM		
Radiator	FAIR • Attn	
Oil Cooler	FAIR • Attn	
OPERATING SYSTEM		
Computer	OK • NG	
Swing	FAIR • Attn	
Travel	FAIR • Attn	
BOOM		
MAIN BOOM		
BOOM TOTAL		
TOP SHEAVE	YES • NO	
JIB		
TOWER		

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN • FAIR • DIRTY	
Operator's Seat	FAIR • Attn	
Glasses	FAIR • Attn	
AirCon	A/C • H/C • H only • C only • None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
リペイントあり、HRメーターなし REPAINTED, HR METER: MISSING		
カニクレーン、4段ブーム SPIDER CRANE, 4-SECTION BOOM		
WEIGHT	-	
HOOK	?t (HOOK CAPACITY: UNKNOWN)	
FREE FALL	YES • NO	
LIFTER	YES • NO	
COMMENT		
起伏シリンダー右油漏れ、左にじみあり		
RIGHT DERRICKING CYLINDER: OIL LEAKING,		
LEFT DERRICKING CYLINDER: OIL OOZING		
作動油タンク油漏れあり HYDRAULIC OIL TANK: OIL LEAKING		
油圧メーター油漏れあり OIL PRESSURE GAUGE: OIL LEAKING		
過巻効かない OVERWINDING PREVENTION: MALFUNCTION		
アウトリガー左Fシリンダー傷、右Fシリンダー油漏れ、右Rシリンダーにじみあり		
FRONT LEFT OUTRIGGER CYLINDER: SCRATCHED,		
FRONT RIGHT OUTRIGGER CYLINDER: OIL LEAKING,		
REAR RIGHT OUTRIGGER CYLINDER: OIL OOZING		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。