

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/4/2	MAKE	KATO	MODEL	KR-10H-L
SERIAL No.	PLATE :	3610081		STAMP :	KR101-0081
HR METER	22673	HR	Odometer	169528	km
TIRE SIZE	11R22.5		YEAR	YR	

ENGINE : MODEL		S/N
Oil leakage	FAIR <input type="radio"/> Attn <input checked="" type="radio"/>	E/G下周り油漏れあり BOTTOM: OIL LEAKING
Blow-By	FAIR <input type="radio"/> Attn <input checked="" type="radio"/>	A LITTLE · MIDDLE · SEVERE
Sound	FAIR <input type="radio"/> Attn <input type="radio"/>	
Oil	FAIR <input type="radio"/> Attn <input type="radio"/>	
Exhaust Color	FAIR <input type="radio"/> Attn <input type="radio"/>	
OPERATION PUMP		
Sound	FAIR <input type="radio"/> Attn <input type="radio"/>	
Oil leakage	FAIR <input type="radio"/> Attn <input type="radio"/>	
Power	FAIR <input type="radio"/> Attn <input type="radio"/>	
COOLING SYSTEM		
Radiator	FAIR <input type="radio"/> Attn <input type="radio"/>	
Oil Cooler	FAIR <input type="radio"/> Attn <input type="radio"/>	
OPERATING SYSTEM		
Computer	OK <input type="radio"/> NG <input type="radio"/>	
Swing	FAIR <input type="radio"/> Attn <input type="radio"/>	
Travel	FAIR <input type="radio"/> Attn <input type="radio"/>	
TRANSMISSION		
Transmission	FAIR <input type="radio"/> Attn <input checked="" type="radio"/>	*1
No. OF GEARS	3	GEARS
No. of DRIVE WHEELS	4	WD
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR <input type="radio"/> Attn <input checked="" type="radio"/>	破れあり CUTS
Inside Cover	FAIR <input type="radio"/> Attn <input type="radio"/>	
Glasses	FAIR <input type="radio"/> Attn <input type="radio"/>	
AirCon	A/C <input type="radio"/> H/C <input type="radio"/> H only <input type="radio"/> C only <input type="radio"/> None <input type="radio"/>	
COMMENT		

BOOM	
No. of Section	6 SECTIONS
CRACK/ENFORCEMENT	FAIR <input type="radio"/> Attn <input type="radio"/>
DERRICKING CYL.	FAIR <input type="radio"/> Attn <input type="radio"/>
EXTENSION CYL.	FAIR <input type="radio"/> Attn <input type="radio"/>
JIB	YES <input type="radio"/> NO <input type="radio"/>
JIB TYPE	STD <input type="radio"/> PWR <input type="radio"/>
MAIN & SUB WIRE	YES <input type="radio"/> NO <input type="radio"/>
HOOK	10t, BALL
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
右サイドパネル一部損傷あり RIGHT SIDE PANEL: A LITTLE DAMAGED	
OUTRIGGERS	
OUTRIGGERS	X <input type="radio"/> H <input checked="" type="radio"/>
OUTRIGGERS COND.	FAIR <input type="radio"/> Attn <input type="radio"/>
COMMENT	
*1 トルコン付近油漏れあり AROUND TORQUE CONVERTER: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。