

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/4/10	MAKE	KOBELCO	MODEL	RK250-6
SERIAL No.	PLATE :	EZ08-10376		STAMP :	EZ08-10376
HR METER	15662	HR	Odometer	45382	km
TIRE SIZE	385/95R25		YEAR	YR	

ENGINE : MODEL S/N

Oil leakage	FAIR	<input checked="" type="radio"/>	Attn	上部油漏れあり UPPER PART: OIL LEAKING
Blow-By	FAIR	<input checked="" type="radio"/>	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	<input checked="" type="radio"/>	Attn	
Oil	FAIR	<input checked="" type="radio"/>	Attn	
Exhaust Color	FAIR	<input checked="" type="radio"/>	Attn	

OPERATION PUMP

Sound	FAIR	<input checked="" type="radio"/>	Attn	
Oil leakage	FAIR	<input checked="" type="radio"/>	Attn	
Power	FAIR	<input checked="" type="radio"/>	Attn	

COOLING SYSTEM

Radiator	FAIR	<input checked="" type="radio"/>	Attn	
Oil Cooler	FAIR	<input checked="" type="radio"/>	Attn	

OPERATING SYSTEM

Computer	OK	<input checked="" type="radio"/>	NG	
Swing	FAIR	<input checked="" type="radio"/>	Attn	
Travel	FAIR	<input checked="" type="radio"/>	Attn	

TRANSMISSION

Transmission	FAIR	<input checked="" type="radio"/>	Attn	
No. OF GEARS	3	GEARS		
No. of DRIVE WHEELS	4	WD		

INTERIOR See Photos. 写真参照

Operator's Seat	FAIR	<input checked="" type="radio"/>	Attn	
Inside Cover	FAIR	<input checked="" type="radio"/>	Attn	
Glasses	FAIR	<input checked="" type="radio"/>	Attn	
AirCon	A/C	<input checked="" type="radio"/>	H/C · H only · C only · None	

COMMENT

--

BOOM

No. of Section	4	SECTIONS	
CRACK/ENFORCEMENT	FAIR	<input checked="" type="radio"/>	Attn
DERRICKING CYL.	FAIR	<input checked="" type="radio"/>	Attn
EXTENSION CYL.	FAIR	<input checked="" type="radio"/>	Attn
JIB	YES	<input checked="" type="radio"/>	NO
JIB TYPE	STD	<input type="radio"/>	PWR <input checked="" type="radio"/>
MAIN & SUB WIRE	YES	<input checked="" type="radio"/>	NO <input type="radio"/>
HOOK	25t, BALL		

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

COMMENT

OUTRIGGERS

OUTRIGGERS	X	<input type="radio"/>	H	
OUTRIGGERS COND.	FAIR	<input checked="" type="radio"/>	Attn	*1

COMMENT

旋回レバーガタ大 SWING LEVER: MUCH LOOSE *1 右R縦シリンダーにじみあり *1 REAR RIGHT VERTICAL CYLINDER: OIL OozING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。