INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/3/4	MAKE	SUMITOMO	MODEL	SH200LPC
SERIAL	NO PLATE			STAMP	200P1-1141
HR METER	1962 HR			YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL S/N		
Oil leakage	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE
Sound	FAIR・Attn	
Oil	FAIR・Attn	
Exhaust Color	FAIR・Attn	
US EPA	YES・NO	
MAIN PUMP		
Sound	FAIR・Attn	
Oil leakage	FAIR・Attn	
Power	FAIR・Attn	
COOLING SYSTEM		
Radiator	FAIR・Attn	
Oil Cooler	FAIR・Attn	
OPERATING SYSTEM		
Swing	FAIR・Attn	
Travel	FAIR・Attn	
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR・Attn	
Inside Cover	FAIR・Attn	
Glasses	FAIR・Attn	*1
AirCon	A/C・H/C・H only・C only・None	
BOOM / ARM / BKT		
Boom	FAIR・Attn	
Boom Cylinder	FAIR・Attn	左右油漏れあり CYLINDERS: OIL LEAKING
Arm	FAIR・Attn	テレスコアーム TELESCOPIC ARM
Arm Cylinder	FAIR・Attn	*2
BKT	FAIR・Attn	
BKT Cylinder	FAIR・Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ( )	
Lever	LONG・WRIST	
Multi	MULTI・2・NO	
ARM-CRANE	YES・NO	
BLADE	YES・NO	
OFFSET	YES・NO	
OFFSET Cylinder	FAIR・Attn	
Piping	YES・NO	Breaker only・Multi
COMMENT		
アタッチメント:クラムシェルバケット ATTACHMENT: CLAMSHELL BUCKET		
スライドCAB SLIDE CAB		
！マーク表示あり(バッテリー液補充)		
WARNING LAMP FOR BATTERY FLUID REFILL: ON		
ブーム背中側ホースひび割れあり SOME HOSE ON BOOM TOP: CRACKED		
ヒーター風が出ない HEATER: NOT BLOWING AIR		
*1 Fフレーム腐食あり WINDSHIELD FRAME: CORRODED & HOLE		
*2 にじみ、サビ、テレスコ部シリンダーサビあり		
*2 OIL OOZING, RUSTY, TELESCOPING CYLINDER: RUSTY		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。