INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2026/10/15	MAKE	HITACHI	MODEL	KH150-3
SERIAL No.	PLATE : 232-0958		STAMP	232-0958	
HR METER	6528 HR	SHOE	760FLAT	YEAR	YR

ENGINE : MODEL	S/N	
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
OPERATION PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Computer	(OK) · NG	
Swing	FAIR · (Attn)	旋回ロック不良 SWING LOCK: MALFUNCTION
Travel	(FAIR) · Attn	
BOOM		
MAIN BOOM	TOP, BOTTOM, 6m × 4, 3m × 2	
BOOM TOTAL	40m	
TOP SHEAVE	(YES) · NO	
JIB		
TOWER		

INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	(FAIR) · Attn	
AirCon	A/C · H/C · H only · C only · (None)	
UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
走行ホースにじみあり SOME TRAVEL HOSE: OIL OOZING		
左右キャタ緩みあり TRACK LINKS: WORN		
WEIGHT	2	
HOOK	40t, 15t, BALL, SWIVEL HOOK	
FREE FALL	(YES) · NO	
LIFTER	YES · (NO)	
COMMENT		
キャタ伸縮シリンダー油漏れあり EXPANDABLE CYLINDERS: OIL LEAKING		
E/Gストップ不良 ENGINE STOPPER: MALFUNCTION		
ブームジョイントピン6本欠 6 BOOM JOINT PINS: MISSING		
ペンダントジョイントピン6本欠 6 PENDANT JOINT PINS: MISSING		
@NARITA YARD		
BOOM: TOP, BOTTOM		
@SAKURA YARD		
BOOM: 6m × 4, 3m × 2		
HOOK: 40t, BALL, SWIVEL HOOK		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。