INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/10/22	MAKE	SUMITOMO	MODEL	SH450HD-3
SERIAL	450A3-5015		STAMP	450A3-5015	
HR METER	10700 HR		YEAR	YR	
CAB/CNP	ROPS CAB / (CAB) / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL S/N		
Oil leakage	FAIR ・(Attn)	*1
Blow-By	(FAIR)・ Attn	A LITTLE・ MIDDLE・ SEVERE
Sound	(FAIR)・ Attn	
Oil	(FAIR)・ Attn	
Exhaust Color	(FAIR)・ Attn	
US EPA	YES ・(NO)	
MAIN PUMP		
Sound	(FAIR)・ Attn	
Oil leakage	(FAIR)・ Attn	
Power	(FAIR)・ Attn	
COOLING SYSTEM		
Radiator	(FAIR)・ Attn	
Oil Cooler	(FAIR)・ Attn	
OPERATING SYSTEM		
Swing	(FAIR)・ Attn	ガタあり SWING: LOOSE
Travel	(FAIR)・ Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN・ FAIR・ (DIRTY)	
Operator's Seat	(FAIR)・ Attn	
Glasses	(FAIR)・ Attn	
AirCon	(A/C)・ H/C ・ H only ・ C only ・ None	
BOOM / ARM / BKT		
Boom	(FAIR)・ Attn	
Boom Cylinder	(FAIR)・ Attn	
Arm	(FAIR)・ Attn	
Arm Cylinder	(FAIR)・ Attn	
ATTACHMENT	(FAIR)・ Attn	
BKT Cylinder	(FAIR)・ Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	
COMMENT		
アタッチメント:小割 ATTACHMENT: SECONDARY CRUSHER		
MAKE: TAGUCHI MC-301		
BKT	STD / SLOPE / NARROW / SKELETON / (OTHER( ))	
Lever	LONG ・ (WRIST)	
Multi	MULTI ・ 2 (・ NO)	
ARM-CRANE	YES ・(NO)	
BLADE	YES ・(NO)	
OFFSET	YES ・(NO)	
OFFSET Cylinder	FAIR ・ Attn	
Piping	(YES)・ NO	Breaker only (・ Multi)
COMMENT		
ブーム周りホースひび割れ多数あり		
SOME HOSES AROUND BOOM: CRACKED		
右サイドカバー変形あり、ラッチ掛からない		
RIGHT SIDE COVER: MUCH DENT, LATCH: UNABLE TO CATCH		
ワンタッチ付 W/ONE-TOUCH		
電気系統異常表示あり WARNINGS DISPLAY FOR ELECTRIC SYSTEM		
エラー表示あり(M0050圧力センサ、M00B0コントローラーミスマッチ)		
(メーカー問い合わせでわかったため写真撮影不可)		
"M0050" & "M00B0" ERRORS DISPLAY		
FOR PRESSURE SENSOR & CONTROLLER MISMATCH (NO PHOTOS)		
*1 ヘッド周り油漏れあり AROUND CYLINDER HEAD: OIL LEAKING		
RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。