

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2019/5/22	MAKE	HITACHI	MODEL	EX40UR-3
SERIAL	1L2P010146		STAMP	NOT FOUND	
HR METER	4463	HR	YEAR	2000	YR
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE		SHOE	300G W/PADS	

ENGINE : MODEL		S/N
Oil leakage	<u>OK</u> · Attn	
Blow-By	<u>OK</u> · Attn	
Sound	<u>OK</u> · Attn	
Oil	<u>OK</u> · Attn	
Exhaust Color	<u>OK</u> · Attn	
US EPA	YES · <u>NO</u>	
MAIN PUMP		
Sound	<u>OK</u> · Attn	
Oil leakage	<u>OK</u> · Attn	
Power	<u>OK</u> · Attn	
COOLING SYSTEM		
Radiator	<u>OK</u> · Attn	
Oil Cooler	<u>OK</u> · Attn	
OPERATING SYSTEM		
Swing	<u>OK</u> · Attn	
Travel	<u>OK</u> · Attn	
INTERIOR		
Operator's Seat	<u>OK</u> · Attn	
Inside Cover	<u>OK</u> · Attn	
Glasses	<u>OK</u> · Attn	
AirCon	A/C · H/C · <u>H only</u> · C only · None	
BOOM / ARM / BKT		
Boom	<u>OK</u> · Attn	
Boom Cylinder	<u>OK</u> · Attn	
Arm	<u>OK</u> · Attn	
Arm Cylinder	<u>OK</u> · <u>Attn</u>	油漏れ小 A LITTLE OIL LEAKING
BKT	<u>OK</u> · Attn	
BKT Cylinder	<u>OK</u> · Attn	にじみあり OIL OOZING

UNDERCARRIAGE :	See Photos. 写真参照
COMMENT	シュープレート剥がれあり SOME SHOE PLATES: MISSED トラックローラー不良 SOME BOTTOM ROLLERS: MALFUNCTION
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER()
Lever	LONG · <u>WRIST</u>
Multi	YES · <u>NO</u>
ARM-CRANE	YES · <u>NO</u>
BLADE	<u>YES</u> · NO
OFFSET	<u>YES</u> · NO
OFFSET Cylinder	<u>OK</u> · Attn
Piping	YES · <u>NO</u> Breaker only · Multi
COMMENT	CAB下へゴミあり FRAME(UNDER CABIN): DENT

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。