

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2024/10/24	MAKE	KOMATSU	MODEL	PC200LC-5
SERIAL	56083		STAMP	56083	
HR METER	15059	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600FLAT	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	*1
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	ガタあり SWING: LOOSE
Travel	FAIR · Attn	HI/LO切替え不良 HI/LO SWITCH: MALFUNCTION
INTERIOR See Photos. 写真参照		
Operator's Seat	FAIR · Attn	フレーム露出、ガタあり DAMAGED, LOOSE
Inside Cover	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	右側油漏れあり RIGHT CYLINDER: OIL LEAKING
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
BKT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
エレベータCAB:ブーム等に油圧を掛けないと上昇しない ELEVATOR CAB: NEED TO SUPPLY IMPLEMENTS WITH HYDRAULIC PRESSURE TO LIFT UP	
CABドアラッチ不良、 外から開かない(内側黄色のワイヤーを引かないと開かない)	
DOOR LATCH: MALFUNCTION, DOOR: UNABLE TO OPEN FROM OUTSIDE (ABLE TO OPEN BY PULLING A YELLOW WIRE)	
E/G低速時動作しない UNABLE TO OPERATE WITH LOW ENGINE SPEED	
*1 油漏れあり(オークション後修理予定)	
*1 OIL LEAKING (REPAIRING AFTER THE AUCTION)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。