

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/3/11	MAKE	HITACHI	MODEL	EX135USR
SERIAL	1ENP010926		STAMP	1ENP010926	
HR METER	10381	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700G	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	油汚れあり OIL STAINS
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	ガタあり SWING: LOOSE
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	*1
Arm	FAIR · Attn	ガタあり LOOSE
Arm Cylinder	FAIR · Attn	油漏れ小 OIL LEAKING
BKT	FAIR · Attn	ガタあり LOOSE
BKT Cylinder	FAIR · Attn	油漏れ小 OIL LEAKING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT (STD / SLOPE / NARROW / SKELETON / OTHER ())	
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
コントロールバルブ周りホース油汚れあり	
HOSES AROUND CONTROL VALVE: OIL STAINS	
ブーム横ホースひび割れあり	
SOME HOSE AROUND LOWER PART OF BOOM: CRACKED	
ファンベルト始動時に鳴きあり	
FAN BELT: NOISES WHEN STARTING THE ENGINE	
アクセル改造あり(ダイヤル→レバー)	
ACCELERATOR: MODIFIED DIAL STYLE TO LEVER STYLE	
A/C冷えない A/C: MALFUNCTION	
*1 左側シリンダーサビ、油漏れあり LEFT CYLINDER: RUSTY, OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。