

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/3/27	MAKE	HITACHI	MODEL	ZX120
SERIAL	HCM1S100K00069862			STAMP	HCM1S100K00069862
HR METER	6929	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	700G

ENGINE : MODEL 4BG1 S/N	
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO
MAIN PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
OPERATING SYSTEM	
Swing	FAIR · Attn ガタあり SWING: LOOSE
Travel	FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	FAIR · Attn
Boom Cylinder	FAIR · Attn 左右にじみあり CYLINDERS: OIL OOZING
Arm	FAIR · Attn 補強、ガタあり REINFORCED, LOOSE
Arm Cylinder	FAIR · Attn
BKT	FAIR · Attn
BKT Cylinder	FAIR · Attn にじみあり OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT (STD / SLOPE / NARROW / SKELETON / OTHER ())	
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO *1
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
CABドア外側ノブ破損あり、外から開かない	
OUTSIDE DOOR KNOB: BROKEN, DOOR: UNABLE TO OPEN FROM OUTSIDE	
CAB内からアクセルコントロール不可(ダイヤル空回りする)	
UNABLE TO CONTROL ACCELERATOR IN CAB	
(ACCELERATOR KNOB: SPINNING WITHOUT CATCHING, NEED TO CONTROL BY THE ACCELERATOR WIRE)	
キーでE/Gオフ不可、デコンプでE/Gオフ	
UNABLE TO STOP THE ENGINE BY THE IGNITION KEY, NEED TO STOP THE ENGINE WITH DECOMPRESSION	
*1 エラー表示、ブザー音あり ERROR DISPLAY, WARNING SOUNDS: ON	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。