

## INSPECTION SHEET 検品書

## OTHER その他

INSPECTION DATE	2025/8/21	CATEGORY	自走式土質改良機 MOBILE SOIL IMPROVEMENT MACHINE			
MAKE	HITACHI		MODEL	SR2000G		
SERIAL	HCM65Y00P00002022		STAMP	NOT FOUND		
HR METER	6208	HR	Odometer	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP <input checked="" type="radio"/> NONE		SHOE	500G	TIRE	

ENGINE	MODEL	4HK1	S/N	
Oil leakage	<input checked="" type="radio"/> FAIR • Attn		Oil	<input checked="" type="radio"/> FAIR • Attn
Blow-By	<input checked="" type="radio"/> FAIR • Attn	A LITTLE • MIDDLE • SEVERE	Exhaust Color	<input checked="" type="radio"/> FAIR • Attn
Sound	<input checked="" type="radio"/> FAIR • Attn		EPA	<input checked="" type="radio"/> YES • NO

CONDITION	FAIR • <input checked="" type="radio"/> Attn
-----------	--

未確認 OPERATION: NOT CHECKED

リアコンベアモーター周り油漏れ、振るい周りポンプにじみあり AROUND REAR CONVEYOR MOTOR: OIL LEAKING, PUMP AROUND SIEVE: OIL OOZING

UNDERCARRIAGE : See Photos. 写真参照
----------------------------------

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR • WORN • UNEVEN WEAR
--	---	-----------	---------------------------

## COMMENT

ファンベルト鳴きあり FAN BELT: NOISES

クレーン付(3段ブーム) W/CRANE MAKE: TADANO TM-ZR263J-EY3245, 3-SECTION BOOM, HOOK: 2.63t

クレーン旋回モーター周り油漏れ小 AROUND SWING MOTOR OF CRANE: OIL LEAKING

本体動作リモコン: 本体ボックス内にあり REMOTE CONTROL: PUTTING IN AN INSIDE OF RIGHT SIDE BODY

付属品: クレーンリモコン(リモコン電源入らない) REMOTE CONTROL FOR CRANE AS SPARE (UNABLE TO TURN ON)

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)

2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。