

INSPECTION SHEET 検品書
CRAWLER CRANE クローラクレーン

INSPECTION DATE	2025/10/8	MAKE	IHI	MODEL	DCH6020
SERIAL No.	PLATE :	HN16	STAMP	HN16	
HR METER	7373 / 857	HR	SHOE	920FLAT	YEAR YR

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	油圧ポンプ油漏れあり PUMP: OIL LEAKING
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Computer	☒ OK · NG	*1
Swing	☒ FAIR · Attn	*2
Travel	☒ FAIR · Attn	
BOOM		
MAIN BOOM	TOP, BOTTOM, 6m × 1, 3m × 2	
BOOM TOTAL	22m	
TOP SHEAVE	YES · ☒ NO	
JIB		
TOWER		

INTERIOR		See Photos. 写真参照
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY	
Operator's Seat	☒ FAIR · Attn	破れ大 TORN
Glasses	☒ FAIR · Attn	
AirCon	A/C · H/C · ☒ H only · C only · None	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
WEIGHT	2	
HOOK	60t, 15t	
FREE FALL	YES · ☒ NO	
LIFTER	YES · ☒ NO	
COMMENT		
アクセル不良(吹けない) ACCELERATOR: MALFUNCTION (UNABLE TO REV UP)		
CABスライドドアロック不良 CAB SLIDE DOOR LOCK: MALFUNCTION		
3mブームラチス曲がり大 SOME LATTICE PIPE OF 3m BOOM: BENT		
*1 画面映り悪い、未確認 MONITOR: VERY BLURRED, NOT CHECKED		
*2 旋回ロックピン入らない SWING LOCK PIN: UNABLE TO LOCK		
@NARITA YARD		
BOOM: TOP, BOTTOM, 6m × 1, 3m × 1		
9m PENDANT × 1, 60t HOOK		
@SAKURA YARD		
BOOM: 3m × 1, 15t HOOK		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。