

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/21	MAKE	HITACHI	MODEL	ZX210LCK-5B
SERIAL	HCMDCKA7J00302233			STAMP	HCMDCKA7J00302233
HR METER	11311	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	800G

ENGINE : MODEL		4HK1	S/N	726140
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn	油漏れ小 OIL LEAKING	
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn	破れあり TORN	
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only · None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn	右側油漏れあり RIGHT CYLINDER: OIL LEAKING	
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn		
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO *1
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
底板周り油漏れあり(コントロールバルブ?)	
BOTTOM (FROM CONTROL VALVE?): OIL LEAKING	
コントロールバルブ油漏れあり CONTROL VALVE: OIL LEAKING	
左サイドカバーラッチ破損あり LEFT SIDE COVER LATCH: BROKEN	
左レバー下油漏れあり	
BOTTOM OF LEFT OPERATION LEVER: OIL LEAKING	
A/Cベルト鳴きあり A/C BELT: NOISES	
*1 バケット警告消えない	
*1 WARNING LAMP FOR BUCKET: UNABLE TO LIGHT OFF	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。