

INSPECTION SHEET 檢品書

OTHER その他

INSPECTION DATE	2025/12/15	CATEGORY	自走式土質改良機 MOBILE SOIL IMPROVEMENT MACHINE				
MAKE	HITACHI			MODEL	SR-G2000		
SERIAL	HCM65X00L00000175			STAMP	NOT FOUND		
HR METER	8437	HR	Odometer		km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS	CNP / CNP / <input checked="" type="radio"/> NONE		SHOE	500G	TIRE	

ENGINE	MODEL	6BG1	S/N				
Oil leakage	<input checked="" type="radio"/> FAIR	Attn		Oil	<input checked="" type="radio"/> FAIR	Attn	
Blow-By	<input checked="" type="radio"/> FAIR	Attn	A LITTLE · MIDDLE · SEVERE	Exhaust Color	<input checked="" type="radio"/> FAIR	Attn	
Sound	<input checked="" type="radio"/> FAIR	Attn		EPA	YES	<input checked="" type="radio"/> NO	

CONDITION	FAIR · <input checked="" type="radio"/> Attn						
上物排出コンペア以外動作しない、停止ボタンで動作止まらない IMPLEMENTS EXCEPT DISCHARGE CONVEYOR: NOT WORKING, UNABLE TO STOP WORKING BY THE STOP BUTTON							
ミキサー周り油漏れ小 AROUND MIXER UNIT: OIL LEAKING							

UNDERCARRIAGE : See Photos. 写真参照				
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2	TIRE WEAR	FAIR · WORN · UNEVEN WEAR	
COMMENT				
メーター: 曇りあり、読み取りにくい INDICATOR: HARD TO READ (PANEL COVER: CLOUDY)				
下側モニター不良 LOWER MONITOR: MALFUNCTION				
クレーン付(3段ブーム、2.63tフック×1、ワイヤー乱巻きあり)				
W/CRANE (NAKE: TADANO 411-082-10910-EY9636): 3-SECTION BOOM, HOOK: 2.63t × 1, WIRE: IRREGULAR WINDING				
E/Gストップ効かない ENGINE STOPPER: MALFUNCTION				
付属品: 手すり、クレーン用ラジコン(ラジコンで動作しない)				
HANDRAILS & RADIO CONTROL FOR CRANE AS SPARE (CRANE: NOT OPERATING BY THE RADIO CONTROL)				
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2			

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。