

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/1/27	MAKE	HITACHI	MODEL	ZH210K-5B
SERIAL	HCMDCSA2J00020257			STAMP	HCMDCSA2J00020257
HR METER	6093	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL 4HK1 S/N	
Oil leakage	FAIR • Attn
Blow-By	FAIR • Attn A LITTLE MIDDLE SEVERE
Sound	FAIR • Attn
Oil	FAIR • Attn
Exhaust Color	FAIR • Attn
US EPA	YES • NO
MAIN PUMP	
Sound	FAIR • Attn
Oil leakage	FAIR • Attn
Power	FAIR • Attn
COOLING SYSTEM	
Radiator	FAIR • Attn 水に油混入あり OIL: MIXED
Oil Cooler	FAIR • Attn
OPERATING SYSTEM	
Swing	FAIR • Attn
Travel	FAIR • Attn *1
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • FAIR • DIRTY
Operator's Seat	FAIR • Attn
Glasses	FAIR • Attn
AirCon	A/C • H/C • H only • C only • None
BOOM / ARM / BKT	
Boom	FAIR • Attn
Boom Cylinder	FAIR • Attn 左傷あり LEFT CYLINDER: SCRATCHED
Arm	FAIR • Attn
Arm Cylinder	FAIR • Attn
ATTACHMENT	FAIR • Attn *2
BKT Cylinder	FAIR • Attn 傷あり SCRATCHED

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • WRIST
Multi	MULTI • 2 • NO
ARM-CRANE	YES • NO
BLADE	YES • NO
OFFSET	YES • NO
OFFSET Cylinder	FAIR • Attn
Piping	YES • NO Breaker only • Multi
COMMENT	
底板欠 SOME UNDER COVER: MISSING	
ブーム背面ホースヒビあり SOME HOSES AROUND OF BOOM: CRACKED	
*1 「走行レバー半開にて走行して下さい」記載あり、全開にすると走行できない	
*1 "PLEASE TRAVEL WITH HALF STROKE OF TRAVEL LEVERS" NOTE, UNABLE TO TRAVEL WITH FULL STROKE POSITION OF TRAVEL LEVERS	
*2 穴、ガタ、Hリンク:クラックあり	
*2 CRACKED, LOOSE, H-LINK: CRACKED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。