

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2026/8/4	MAKE	E. FALCK SCHMIDT	MODEL	TS-17
SERIAL No.	PLATE : 807			STAMP : NOT FOUND	
HR METER	661	HR	Odometer	—	km
YEAR	YR				
CHASSIS	MODEL —			No. —	
SHOE				TIRE SIZE	190-8
MAX HIGHT	17.0			m	
	MAX WEIGHT			200 kg	

ENGINE : MODEL S/N	
Oil leakage	FAIR • Attn
Blow-By	FAIR • Attn A LITTLE • MIDDLE • SEVERE
Sound	FAIR • Attn
Oil	FAIR • Attn
Exhaust Color	FAIR • Attn
US EPA	YES • NO
OPERATION PUMP	
Sound	FAIR • Attn
Oil leakage	FAIR • Attn
Power	FAIR • Attn
COOLING SYSTEM	
Radiator	FAIR • Attn
Oil Cooler	FAIR • Attn
TRANSMISSION & TRAVEL	
T/M TYPE	AT • MT No. OF GEARS — GEARS
Transmission	FAIR • Attn
4WD	4WD • 2WD 3WD
Travel	FAIR • Attn
Swing	FAIR • Attn
FOOT BRAKE	FAIR • Attn
PARKING BRAKE	FAIR • Attn
BOOM	
No. of Section	3 SECTIONS
DERRICKING CYL.	FAIR • Attn *1
EXTENSION CYL.	FAIR • Attn

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN • FAIR • DIRTY
Operator's Seat	FAIR • Attn
Glasses	FAIR • Attn
AirCon	A/C • H/C • H only • C only • None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR • WORN • UNEVEN WEAR
COMMENT	
OUTRIGGERS X • H OUTRIGGERS COND. FAIR • Attn	
COMMENT	
電動駆動 ELECTRIC DRIVE VEHICLE バケット外れあり(付属品扱い)、バケット固定ピン欠 BUCKET: COME OFF, BUCKET PIN: MISSING バケット側操作レバー: ブーム起伏側反応しない (バケットが付いていないため届く範囲での操作しかできないので バケットを付けたら動く可能性あり、安全装置?) OPERATION LEVER AT BUCKET PART: NOT WORKING FOR BOOM DERRICKING (POSSIBLE TO OPERATE IF ATTACHING THE BUCKET, SAFETY DEVICE: WORKING?) *1 後ろ側にじみあり REAR CYLINDER: OIL OOOZING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。