

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2024/4/10	MAKE	KATO	MODEL	KR-35H-V2
SERIAL No.	PLATE :	2410131	STAMP :	KR353-0131	
HR METER	92534	HR	Odometer	89999	km
TIRE SIZE	445/95R25	YEAR	YR		

ENGINE : MODEL	S/N
Oil leakage	<input type="radio"/> FAIR · Attn
Blow-By	<input type="radio"/> FAIR · <input type="radio"/> Attn A LITTLE · MIDDLE · <input checked="" type="radio"/> SEVERE
Sound	<input type="radio"/> FAIR · Attn
Oil	<input type="radio"/> FAIR · Attn
Exhaust Color	<input type="radio"/> FAIR · Attn
OPERATION PUMP	
Sound	<input type="radio"/> FAIR · Attn
Oil leakage	<input type="radio"/> FAIR · Attn
Power	<input type="radio"/> FAIR · Attn
COOLING SYSTEM	
Radiator	<input type="radio"/> FAIR · Attn
Oil Cooler	<input type="radio"/> FAIR · Attn
OPERATING SYSTEM	
Computer	<input checked="" type="radio"/> OK · NG
Swing	<input type="radio"/> FAIR · Attn
Travel	<input type="radio"/> FAIR · Attn

TRANSMISSION	
Transmission	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn *1
No. OF GEARS	4 GEARS
No. of DRIVE WHEELS	4 WD

INTERIOR See Photos. 写真参照	
Operator's Seat	<input type="radio"/> FAIR · Attn
Inside Cover	<input type="radio"/> FAIR · Attn
Glasses	<input type="radio"/> FAIR · Attn
AirCon	<input checked="" type="radio"/> A/C · H/C · H only · C only · None

COMMENT
CABへコミあり CAB: DENT
上部右サイドカバー割れあり
RIGHT SIDE COVER OF UPPER PART: CRACKED

BOOM	
No. of Section	5 SECTIONS
CRACK/ENFORCEMENT	<input type="radio"/> FAIR · Attn
DERRICKING CYL.	<input type="radio"/> FAIR · Attn
EXTENSION CYL.	<input type="radio"/> FAIR · Attn
JIB	<input checked="" type="radio"/> YES · NO シリンダー油漏れあり CYLINDER: OIL LEAKING
JIB TYPE	STD · <input checked="" type="radio"/> PWR
MAIN & SUB WIRE	<input checked="" type="radio"/> YES · NO
HOOK	35t, 22.5t, BALL

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

COMMENT
左サイドカバー割れあり LEFT SIDE COVER: CRACKED
エアドライヤー異音あり AIR DRYER: NOISES

OUTRIGGERS	
OUTRIGGERS	<input checked="" type="radio"/> X · H
OUTRIGGERS COND.	<input type="radio"/> FAIR · <input checked="" type="radio"/> Attn *2

COMMENT	
伸縮非常用で操作	
BOOM: NEED TO OPERATE WITH THE EMERGENCY MODE TO TELESCOPE	
F42ブーム長検出部零調エラー、E3本体部音声用電源低下発生、アキュム低圧、エラー警報表示あり	
"F42," "E3," & MORE ERRORS DISPLAY	
(BOOM ZERO ADJUSTMENT OF BOOM LENGTH DETECTOR, LOW BATTERY POWER FOR SOUNDS OF MAIN BODY PART, LOW PRESSURE OF ACCUMULATOR, ERROR SIGNAL)	
ボンネットひび割れあり ENGINE HOOD: CRACKED	
*1 ミッション付近油漏れあり AROUND TRANSMISSION: OIL LEAKING	
*2 右縦シリンダー油漏れあり REAR RIGHT VERTICAL CYLINDER: OIL LEAKING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。