

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2026/7/15	MAKE	CAT	MODEL	315FLCR
SERIAL	CAT0315FKTDY10977			STAMP	CAT0315FKTDY10977
HR METER	8779 / 8783		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	500G PADS

ENGINE : MODEL		C4.4	S/N	W7N28470
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn	*1	
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only · None
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn		
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn	油漏れ小 OIL LEAKING	
ATTACHMENT	FAIR	Attn	ガタあり LOOSE	
BKT Cylinder	FAIR	Attn	傷あり SCRATCHED	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
シューパッド摩耗大 RUBBER PADS: ALMOST GONE	
BKT	STD / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO *2
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi
COMMENT	
付属品: 手すり HANDRAIL AS SPARE	
*1 ガタあり、	
旋回していると1回転しないうちにアイドルダウンして旋回がガツンと止まる、	
その後レバーを倒しても旋回しなくなるが	
ブーム/アーム等レバーを入れてアイドルアップした後に	
再度旋回できるようになるがまた同様に止まる	
*1 SWING: LOOSE,	
SUDDENLY STOPPING SWINGING BY IDLE DOWN WHILE MAKING ONE FULL TURN,	
AFTER THAT, NOT SWINGING BY THE OPERATION LEVER	
(ABLE TO SWING AFTER INCREASING THE IDLE SPEED	
BY OPERATING ANYTHING EXCEPT SWING BUT ALSO STOPPING AGAIN)	
*2 半径表示変わらない OPERATING RADIUS: NOT CHANGING TO DISPLAY	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。