

## INSPECTION SHEET 検品書

## Rollers ローラー

MAKE	KAWASAKI		MODEL	K20II	
SERIAL	KR20D-2170		STAMP	KR20D-2170	
HR METER	1254(ERROR)	HR	Odometer	- KM	
YEAR	1990	YR	CAB/CNP	CAB / <u>CNP</u> /	NONE
No. PLATE	有・ <u>無</u>	No.	書類	車検	一時抹消 その他 無

<b>ENGINE : MODEL</b>		<b>S/N</b>	<b>TIRE / DRUM :</b>	<b>See Photos. 写真参照</b>	
Oil leakage	<u>OK</u> · Attn		<b>COMMENT</b>		
Blow-By	<u>OK</u> · Attn		TIRE: 9.00-20 10PR		
Sound	<u>OK</u> · Attn		タイヤサイド切れ		
Oil	<u>OK</u> · Attn		CUTS ON TIRE(SIDE)		
Exhaust Color	<u>OK</u> · Attn				
US EPA	YES · <u>NO</u>				
<b>OPERATION PUMP</b>			<b>BATTERY</b> OK · <u>NG</u>		
Sound	<u>OK</u> · Attn				
Oil leakage	<u>OK</u> · Attn		給水ホース破損		
Power	<u>OK</u> · Attn		散油ホース切れ		
<b>COOLING SYSTEM</b>			キャノピー割れ有		
Radiator	OK · <u>Attn</u>	ホース漏れ LEAKING FROM HOSE.	WATER SUCTION HOSE: DAMAGED		
Oil Cooler	OK · Attn	-	OIL SPRINKLER HOSE: CUT		
<b>TRANSMISSION &amp; TRAVEL</b>			CNP: PARTLY DAMAGED		
T/M TYPE	PS · <u>DD</u>				
Transmission	<u>OK</u> · Attn				
Travel	<u>OK</u> · Attn				
FOOT BRAKE	<u>OK</u> · Attn				
PARKING BRAKE	<u>OK</u> · Attn				
<b>INTERIOR</b>					
Operator's Seat	<u>OK</u> · Attn				
Inside Cover	OK · Attn	-			
Glasses	OK · Attn	-			
AirCon	A/C · H/C · H only · C only	<u>None</u>			
<b>OTHERS</b>					
Vibratory	OK · Attn	-			
Watering	OK · <u>Attn</u>	散水ホース切れ SPRINKLER HOSE: CUT			
Articulate	OK · Attn	-			